

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation			
ESC File No.	C09E001H P		Project Name:	Volcano Mesa Subdivision			
NPDES Id. No.	NMR1004HB Lo		_ocation:	6800 Oakridge St. NW			
10/1	2/2023	Owner			Contractor		
Operator		DH Horton			Salls Brothers		
Contact name & title		Todd Warmkessel			Mathew Dyer		
e-mail		TWarmkessel@drhorton.com			mdyer@sallsbrothers.com		
Contact Phone #		225-4760			252-9245		
COA Inspector		Doug Hughes			Start/End Time: 2:40 PM		PM
Construction Phase:		Home Construction & Final Stabilization					
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up
Weath	er at time of i	inspection? Cloudy			Temperature: ~ 69		
Estimated	date of last s	storm 0.25" o	or greater		9/13/2023		
Item							
		Deficiency/ Corrective Action					
Number						• •	
1	The up-to-date SWPPP and inspection reports weren't available on-site. None of the construction						
	personel onsite could locate the SWPPP, so we called the phone number for Todd Warmkessel on the						
	posting and left a voice message. He didn't call back until the next day.						
2							
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspection Reports		Requested	Latest report Date:		none yet	
Notes:							
	•						

City of Albuquerque Stormwater Inspector Signature and date:

10/13/2023

Contact information:

Doug Hughes (505-924-3420)

jhughes@cabq.gov

James D. Hughes