



Project Name:		Valle Prado Unit 3					
Location:		Rainbow & woodmont					
Site Contact Name & Agency	Brent Lesley - DR Horton			ESC File No.	C09E011		
	PBLesley@drhorton.com			NPDES Id. No.	NMR12B443		
Inspection Date:	03/12/19	Start/End Time:	1420/1430hrs				
CoA Stormwater Inspector:		Timothy Sims, Stormwater Inspector					
Present Phase of Construction:	Stabilized						
Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"	
						311/Complaint	Follow Up

Temperature: ~ 57*

Clarify amount: (i.e.. <1/4" to >3/4"): yes, >3/4"

[illegible]

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes		
2.3.3	Construction and domestic wastes		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	Site is stabilized

City of Albuquerque Stormwater Inspector Signature and date: _____

Contact information: Timothy Sims, 505-803-6155 or 03/12/19

tsims@cabq.gov