LT Building Corp

LT Building Corp -Bedrock

Storm Water Compliance Inspection Form

Owner - NMR1005SI / Operator NMR1005S8



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine	Date: 10-18-2023	Time: 11:48 AM
Permit Tracking #:	Inspector Name: John Paiz	Qualifications: Inspector
Owner - NMR1005SI / Operator NMR1005S8		

Date and Amount of Last Recordable Storm Event:

Construction Time Line:

Current Weather Conditions: Clear

Action	Start Date	Date Complete
Initial BMP Installation	09-14-2023	09-14-2023
Clearing and Grubbing	09-15-2023	
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?	\boxtimes			
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			\boxtimes	
Silt Fence		\boxtimes		
Wattles/Filter Sock	\boxtimes			
Inlet Protection			X	
Cut Back Curbs			X	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			
Material Storage	\boxtimes			
Dust Control	\boxtimes			Water truck onsite
Street Sweeping	\boxtimes			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.			\boxtimes	
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			\boxtimes	

LT Building Corp

LT Building Corp -Bedrock

Owner - NMR1005SI / Operator NMR1005S8

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	\boxtimes			Inside trailer
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?	\boxtimes			
Are inspector qualifications in the SWPPP?	\boxtimes			
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?			\boxtimes	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Bedrock ABQ Investors, LLC 10-18-2023					
	Name	Signature	Date			
Operato	: William Leahy		10-18-2023			
	Name	Signature	Date			

Additional Comments:

LT Building Corp -Bedrock



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Paseo del Norte	Maintenance		10-18-2023		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

たれ ۷

Inspector: John Paiz

Name

Signature

10-18-2023

Date

