



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Durango at the Trails				
Location:	Woodmont & Rainbow				
Site Contact Name & Agency	Hakes Brothers	ESC File No.	C09E012		
	Greg H.	NPDES Id. No.	NMR12BG99		
Inspection Date:		Start/End Time:			
CoA Stormwater Inspector:	Timothy Sims, Stormwater Inspector				
Present Phase of Construction:	stabilized				
Type of Inspection:					
	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection? Clear	Temperature: ~ 37*
---	--------------------

Has there been a storm event since site was Permitted?

Clarify amount: (i.e.. <1/4" to >3/4"):

Inspection

CGP Section	BMP / Action	Maintenance or Corrective Action Required	Location and Notes
1.5	PC		
2.2.1	Provide and maintain Waters of the US <50ft		
2.2.3	Sediment control along a		
2.2.3	Sediment control along any per		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes		
2.3.3	Construction and domestic wastes		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	NO	
4	Self Inspection Reports		Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	SITE STABILIZED - 02.08.2019 tes

City of Albuquerque Stormwater Inspector Signature and date: _____
 Contact information: Timothy Sims, 505-803-6155 or tsims@cabq.gov 2/8/2019