

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	C09E013		roject Name:	Catalonia at The Trails			
NPDES Id. No.	NMR1002ET		ocation:	Woodmont Ave. and Paseo Del Norte			
0, _ , _ 0		Owner		Contractor			
Operator		PV Catalonia, LLC					
Contact name & title		Kevin Wechter					
e-mail Contact Phone #		kwechter@pacventures.com 858-625-0100					
COA Inspector		Doug Hughes			Start/End Time: 11am		
Construction Phase:					n & Final Stabilization		
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
	er at time of i		Rair	ו	Tempe	rature: ~	76
		storm 0.25" o			6/27/2022		
Item							
	Deficiency/ Corrective Action						
Number							
1	none waiting for grass to grow						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports	Requested	Latest re	port Date:	6/9/20	22

Notes:

All buildable lots have been transferred to DR Horton. Seed and Hydromulch were being applied which satisfys the stabilization criteria of CGP 2.2.14.a but not the Final Stabilization Criteria of CGP 2.2.14.c. The inspection frequincy may be reduced to once per month after all areas under control of PV, Catalonia, LLC have been mulched. The Pond south of the site belongs to the Community Association and is being stabilized with this project.

The SWPPP is on the back of the Posting on Woodmont across from the south pond.

6/28/2022 City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505-924-3420) jhughes@cabq.gov

James D. Hughes