

City of Albuquerque Stormwater Construction Site Inspection Report

			General In	nformation				
ESC File No.	C09E			Catalonia at The Trails				
NPDES Id. No.	NMR10	002ET Lo	cation:	W	oodmont Ave. and Paseo Del Norte			
4/25/2022		Owner			Contractor			
		PV Trails Albuquerque, LLC						
Contact name & title		Kevin Wechter					_	
e-mail Contact Phone #		kwechter@pacventures.com 858-625-0100						
COA Inspector		Doug Hughes			Start/End Time:	1:30pm	_	
Construction Phase:		Home Construction			-	•		
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint Follow Up	_	
	er at time of i		clea		Tempera		=	
		storm 0.25" or greater			3/23/2022			
			8					
Item	Deficiency/ Corrective Action							
Number								
1	The SWPPP wa	WPPP was available at the staging area but it wasn't up-to-date. The map didn't show the staging						
	area. The NOIs	NOIs were missing and two additional property owner's NOIs are required. Stabilization ar		required. Stabilization areas				
	need to be sho	own on the map with specifications for the common areas, the ponds, the dirt portion of						
		est of Catalonia, and the staging area.						
2	Construction and domestic waste was on the ground at the staging area. Waste must be placed in				aste must he placed in a	_		
2	container with a lid.						_	
3	Washout on the ground at the Staging are must be removed.							
4	Silt fence and stabilization is needed around the dirt portion of Woodmont East of Catalonia.							
5		eded across the south side of the site. Hydromulch being placed there contains only						
	enough fiber t	to cover about 50% of the ground. It is too thin and won't last very long. BMPs and						
	inspections must continue until Final Stabilization Criteria 2.2.14.c is satisfied and verified by the city.					ed and verified by the city.		
6							_	
O								
							_	
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	4/28/2022		

Notes:	
All but the	south row of lots have been transferred to DR Horton. Stabilization was in progress. The Pond
east of Wo	podmont has been Transferred into the Villa Prado Project and expanded. The pond north of
this site ha	as been transferred to the Preserve at Woodmont. The Pond south of the site belongs to the
Communit	ty Association and is being stabilized with this project.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov