

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation				
ESC File No.	C09E013		roject Name:	Catalonia at The Trails				
NPDES Id. No.	NMR1002ET L		ocation:	Woodmont Ave. and Paseo Del Norte				
,,12,2020		Owner	-		Contractor			
0 0 0 0 0 0 0		PV Catalonia, LLC						
Contact name & title		Kevin Wechter						
e-mail Contact Phone #		858-625-010	acventures.com					
COA Inspector		Doug Hughes			Start/End Time: 11am			
Construction Phase:					n & Final Stabilization			
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of		inspection?	Rair	า	Temper	ature: ~	98	
		storm 0.25" oi	r greater		3/17/2023			
ltem Number	Deficiency/ Corrective Action							
1	Owner Terminated coverage 9/7/2022 and made reasonably successful attempt to stabilize HOA Tracts. However silt fence (SF) was left behind on west side. Please remove SF.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	Requested	Latest re	port Date:	N/A		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov