

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C09E013_DR		roject Name:	DR Horton at Catalonia at The Trails				
NPDES Id. No.	NMR10040T		ocation:	Woodmont Ave. and Paseo Del Norte				
4/6/2022		Owner			Contractor			
Operator		DR Horton Inc						
Contact name & title		Joseph Cordero						
e-mail Contact Phone #		Jcordero@DRHorton.com 991-5266						
COA Inspector		Doug Hughes			Start/End Time: 3:30pm			
Construction Phase:					n & Final Stabilization			
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	inspection?	clea	r		rature: ~	71	
	Estimated date of last storm 0.25" or greater 3/23/2022							
Item								
	Deficiency/ Corrective Action							
Number								
1	The SWPPP map wasn't up-to-date.							
2								
3								
4								
5								
2.1	Discharge off site? (Y/N)		no					
4	Self Inspec	tion Reports	Requested	Latest re	port Date:	3/31/20	022	

Notes:					
All but the south row of lots have been transferred to DR Horton.					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

jhughes@cabq.gov

Doug Hughes (505-924-3420)

4/8/2022

James D. Hughes