

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C09E013		oject Name:		Catalonia at The Trails			
NPDES Id. No.	NMR1002ET		cation:	V	Woodmont Ave. and Paseo Del Norte			
7/12/2023		Owner			Contractor			
Operator		PV Catalonia, LLC						
Contact name & title		Kevin Wechter						
e-mail			acventures.com	1				
Contact Phone #		858-625-0100						
COA Inspector		Doug Hughes			Start/End Time:	End Time: 11am		
Construction Phase:		Home Construction & Final Stabilization						
Type of Inspection:		Regular Storm Event Past Storm			Event >0.25" 311/Complaint Follow Up			
Weather at time of i		nspection?	Rai	n		ature: ~	98	
Estimated date of last storm 0.25" or greater 3/17/2023								
Item	Definion and Compositive Astion							
Number	Deficiency/ Corrective Action							
1	Owner Terminated coverage 9/7/2022 and made reasonably successful attempt to stabilize HC							
-	However silt fence (SF) was left behind on west side. Please remove SF.							
2.1	Discharge off site? (Y/N)		no	no				
4	Self Inspection Reports		Requested	Latest re	port Date:	N/A	\	
					-			
Notes:								
	•							

City of Albuquerque Stormwater Inspector Signature and date: 7/18/2023

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

James D. Hughes