

PV Trails: Catalonia

Storm Water Compliance Inspection Form

NMR1002ET



PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine	Date: 07-15-2021	Time: 3:43 PM
Permit Tracking #: NMR1002ET	Inspector Name: Mario Alderete	Qualifications: Inspector
Current Weather Conditions: Thunderstorms (Chance)	Date and Amount of Last Recordable Storm Ev	vent: 07-14-2021 .75

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	04-01-2021	
Clearing and Grubbing	05-01-2021	
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			\boxtimes	
Silt Fence		\boxtimes		
Wattles/Filter Sock			\boxtimes	
Inlet Protection		X		
Cut Back Curbs			\boxtimes	
Waste Management			\boxtimes	
Vehicle Tracking Control	\boxtimes			
Material Storage			\boxtimes	
Dust Control			\boxtimes	
Street Sweeping	\boxtimes			Sweeping street as needed
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			\boxtimes	

PV Trails Albuquerque, PV Trails: Catalonia LLC

NMR1002ET

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?		\boxtimes		Book not on site
Was the SWPPP updated at the time of the inspection?				Book not on site
Are all certification pages signed?			\boxtimes	
Are inspector qualifications in the SWPPP?			\boxtimes	
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?				

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner: PV Trails Albuquerque, LLC

Name

Signature Rico Hallegos

Operator: Rico Gallegos

Name

Signature

Additional Comments:

07-15-2021

Date

Date





Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
West perimeter	Corrective Action	Need to repair silt fence	06-24-2021		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

lere -

07-15-2021

Inspector: Mario Alderete Name

Signature

Date

Inspection Photos



1-24-21



6-17-21



6-24-21