**City of Albuquerque Stormwater Construction Site Inspection Report**

## General Information

| | | | |
|---|---|---|---|
| ESC File No. | C11E004 | Project Name: | Rosa Parks Stockpile Yard |
| NPDES Id. No. | NMR100501 | Location: | Rosa Parks and Kimmick |

| | | |
|---|---|---|
| 8/14/2025 | Owner | Contractor |
| Operator | Steve.Metro@wilsonco.com NMR100504 | Guzman Construction |
| Contact name & title | Altagracia Pena NMR100501 | Lupita Pena, NMR1004ZB |
| e-mail | lupita@guzmancs.com | lupita@guzmancs.com |
| Contact Phone # | 505-341-8591 | AP452-0663 SM280-4553 |

| | | | |
|---|---|---|---|
| **COA Inspector** | **Chancellor English** | Start/End Time: | 2pm |
| Construction Phase: | Stockpiles and construction support | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Type of Inspection: | | Regular | | Storm Event | | Post Storm Event >0.25" | | 311/Complaint | Follow Up |

| | | | |
|---|---|---|---|
| Weather at time of inspection? | Clear | Temperature: ~ | 90 |
| Estimated date of last storm 0.25" or greater | | 7/3/2025 | |

| Item Number | Deficiency/ Corrective Action | | | |
|---|---|---|---|---|
| 1 | None | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 2.1 | Discharge off site? (Y/N) | no | | |
| 4 | Self Inspection Reports | Yes | Latest report Date: | 7/30/2025 |

| |
|---|
| Notes: QR code for SWPPP and Inspection reports. |
| Prior violations for Posting, SWPPP, BMPs, and stabilization |
| |
| |
| |
| |

City of Albuquerque Stormwater Inspector Signature and date: 8/14/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English