City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C11E004	Project Name:	Rosa Parks Stockpile Yard
NPDES Id. No.	NMR100501	Location:	Rosa Parks and Kimmick

12/12/2025	Owner	Contractor
Operator	Steve.Metro@wilsonco.com NMR100504	Guzman Construction
Contact name & title	Altagracia Pena NMR100501	Lupita Pena, NMR1004ZB
e-mail	lupita@guzmancs.com	lupita@guzmancs.com
Contact Phone #	505-341-8591	AP452-0663 SM280-4553

COA Inspector	**Chancellor English**	Start/End Time:	10:30am
Construction Phase:	Stockpiles and construction support		

Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"		311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	55
Estimated date of last storm 0.25" or greater		11/20/2025	

Item Number	Deficiency/ Corrective Action			
1	None			
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	Yes	Latest report Date:	11/19/2025

Notes:	
Prior violations for Posting, SWPPP, BMPs, and stabilization have been mitigated	
Silt fence is okay.	

City of Albuquerque Stormwater Inspector Signature and date: 12/12/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English