

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C11E	.004 F	Project Name:	Rosa Parks Stockpile Yard				
NPDES Id. No.	NMR1004ZB		ocation:		Rosa Parks and Kimmick			
8/1	0/2022	Owner			Contractor			
Operator			Steve.Metro@wilsonco.com NMR100504		Guzman Construction			
Contact name & title		Altagracia Pena NMR100501			Lutita Pena, NMR1004ZB			
e-mail		lupita@guzmancs.com			lupita@guzmancs.com			
Contact Phone #		505-341-8591			AP452-0663 SM280-4553			
COA Inspector		Doug Hughes			Start/End Time: 3-4pm			
	ction Phase:				aging			
Type of Ir	nspection:	Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	inspection?	Clou	ldy	Tempera	ature: ~	90	
Estimated	Estimated date of last storm 0.25" or greater 7/24/2022							
Item								
	Deficiency/ Corrective Action							
Number								
1	BMPs were missing.							
2	Neither the NOIs nor Stabilization has been provided for Tracts 1-3 of Block 6.							
3	Three NOIs and operator Certifications are missing from the SWPPP. The signature on the SWPPP							
	Cerifications must match the signature NOIs, specificly Lupeta, Altagraca, and Steve Certified the NOIs							
	and must Certify the SWPPP with their wet signatures. Deligation of Authority if applicable, must signed							
	by the same corporate officer that signed the NIOs. Verify that signatures meet the criteria in CGP							
	Appendix G.11	1.						
4								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	n/a	Latest re	port Date:	none	2	
Notes:								
The SWPPP is in Tom Meier's pickup onsite Ph 453-8625 thomas.Meier02@icloud.com. Tom is Guzman's								
DA. Tracts 1-5 Block 6 are entirely covered by recent land disturbing activities. There is also a large area of land disturbance on the portion of Tract 1 Blk 2. The site is mostly inactive, with the exception of								
of land dis	sturbance on	the portion o	of Tract 1 Blk 2.	The site is m	ostly inactive,	with the except	tion of	
water true	cks going bacl	k and forth be	etween the hydi	rants on the	east and La Cu	uentista III on th	ne west.	

City of Albuquerqu	ue Stormwater Inspector Signature and date:	
Contact information:	Doug Hughes (505-924-3420)	-7.
	ihuahaa Qaaha aay	Ja

8/11/2022 James D. Hughes

jhughes@cabq.gov