



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C11E004	Project Name:	Rosa Parks Stockpile Yard
NPDES Id. No.	NMR1004ZB	Location:	Rosa Parks and Kimmick
8/25/2022	Owner	Contractor	
Operator	Steve.Metro@wilsonco.com NMR100504	Guzman Construction	
Contact name & title	Altagracia Pena NMR100501	Lutita Pena, NMR1004ZB	
e-mail	lupita@guzmancs.com	lupita@guzmancs.com	
Contact Phone #	505-341-8591	AP452-0663 SM280-4553	
COA Inspector	Doug Hughes	Start/End Time:	1:30-2pm
Construction Phase:	Staging		
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25" 311/Complaint Follow Up
Weather at time of inspection?	Cloudy	Temperature:	~ 90
Estimated date of last storm 0.25" or greater	7/24/2022		

Item Number	Deficiency/ Corrective Action		
1	none - Previous violations (SWPPP, NOIs, BMPs, Posting, and Stabilization has been provided for Tracts 1-3 of Block 6) had been mitigated.		
2			
3			
4			
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	n/a	Latest report Date: none

Notes:	
<p>The SWPPP is in Tom Meier's pickup onsite Ph 453-8625 thomas.Meier02@icloud.com. Tom is Guzman's DA. Tracts 1-5 Block 6 are entirely covered by recent land disturbing activities. There is also a large area of land disturbance on the portion of Tract 1 Blk 2. The site is mostly inactive, with the exception of water trucks going back and forth between the hydrants on the east and La Cuentista III on the west.</p>	

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Doug Hughes (505-924-3420)
jhughes@cabq.gov

8/30/22

James D. Hughes