



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	C11E004	Project Name:	Rosa Parks Stockpile Yard		
NPDES Id. No.	NMR100501	Location:	Rosa Parks and Kimmick		
7/18/2024	Owner	Contractor			
Operator	<a href="mailto:Steve.Metro@wilsonco.com">Steve.Metro@wilsonco.com</a> NMR100504		<a href="#">Guzman Construction</a>		
Contact name & title	Altagracia Pena NMR100501		Lutita Pena, NMR10042B		
e-mail	<a href="mailto:lupita@guzmanacs.com">lupita@guzmanacs.com</a>		<a href="mailto:lupita@guzmanacs.com">lupita@guzmanacs.com</a>		
Contact Phone #	505-341-8591		AP452-0663 SM280-4553		
COA Inspector	Chancellor English		Start/End Time:	2pm	
Construction Phase:	Stockpiles				
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input checked="" type="checkbox"/> Follow Up
Weather at time of inspection?	Clear		Temperature: ~	90	
Estimated date of last storm 0.25" or greater	6/30/2024				
Item Number	Deficiency/ Corrective Action				
1	The perimeter silt fence needs maintenance in violation of CGP Part 2.1.4. Required mitigation: Ensure all stormwater controls are maintained and remain in effective operating condition during the permit coverage and are protected from activities that would reduce their effectiveness per CGP Part 2.1.4.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	7/17/2024	

Notes:	QR code for SWPPP and Inspection reports.
Prior violations for Posting, SWPPP, BMPs, and stabilization	
Weeds are becoming overgrown again and exceeding the 4" width and 4" height allowed by City Ordinance 9-8-4.	

City of Albuquerque Stormwater Inspector Signature and date: 7/23/2024  
Contact information: Chancellor English (505) 924-3325  
[english@cabq.gov](mailto:english@cabq.gov)

*Chancellor English*