



**City of Albuquerque Stormwater Construction Site Inspection Report**

General Information					
ESC File No.	C11E004	Project Name:	Rosa Parks Stockpile Yard		
NPDES Id. No.	NMR1004ZB	Location:	Rosa Parks and Kimmick		
8/25/2022	Owner	Contractor			
Operator	<a href="mailto:Steve.Metro@wilsonco.com">Steve.Metro@wilsonco.com</a> NMR100504		Guzman Construction		
Contact name & title	Altagracia Pena NMR100501		Lutita Pena, NMR1004ZB		
e-mail	<a href="mailto:lupita@guzmancs.com">lupita@guzmancs.com</a>		<a href="mailto:lupita@guzmancs.com">lupita@guzmancs.com</a>		
Contact Phone #	505-341-8591		AP452-0663 SM280-4553		
<b>COA Inspector</b>	<b>Doug Hughes</b>		Start/End Time:	1:30-2pm	
Construction Phase:	Staging				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Cloudy		Temperature:	~	90
Estimated date of last storm 0.25" or greater	7/24/2022				
Item Number	Deficiency/ Corrective Action				
1	none - Previous violations (SWPPP, NOIs, BMPs, Posting, and Stabilization has been provided for Tracts 1-3 of Block 6) had been mitigated.				
2					
3					
4					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	n/a	Latest report Date:	none	
<b>Notes:</b>					
The SWPPP is in Tom Meier's pickup onsite Ph 453-8625 <a href="mailto:thomas.Meier02@icloud.com">thomas.Meier02@icloud.com</a> . Tom is Guzman's DA. Tracts 1-5 Block 6 are entirely covered by recent land disturbing activities. There is also a large area of land disturbance on the portion of Tract 1 Blk 2. The site is mostly inactive, with the exception of water trucks going back and forth between the hydrants on the east and La Cuentista III on the west.					

City of Albuquerque Stormwater Inspector Signature and date:  
 Contact information: Doug Hughes (505-924-3420)  
[jhughes@cabq.gov](mailto:jhughes@cabq.gov)

---