Guzman - Rosa Parks Stockpile Yard



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 03-26-2025 Time: 11:25 AM

Permit Tracking #: NMR1004ZB Inspector Name: John Paiz Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 07-02-2024 1.07"
Very Light Rain Showers (Isolated)

Construction Time Line:

Construction Time Line:									
Action	Start Date	Date Complete							
Initial BMP Installation									
Clearing and Grubbing									
Utility Installation									
Construction of Structure									
Final Stabilization									

Site Walk

Site Walk:				
Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?				
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence		\boxtimes		
Wattles/Filter Sock			\boxtimes	
Inlet Protection		\boxtimes		
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control			\boxtimes	
Material Storage	\boxtimes			
Dust Control	\boxtimes			
Street Sweeping	\boxtimes			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.			\boxtimes	
Discharge Points			\boxtimes	
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			
Other			\boxtimes	

03-26-2025

Date

Guzman - Rosa Parks Stockpile Yard

SWPPP Information:

Question	Yes	No	N/A	Comment		
Is the SWPPP kept on site?				With superintendent		
Was the SWPPP updated at the time of the inspection?		\boxtimes				
Are all certification pages signed?						
Are inspector qualifications in the SWPPP?						
Is there a copy of the NOI and Acknowledgement letter?						
Is there a delegation letter in the SWPPP?	\boxtimes					
Was the last inspection/CAL certified?			\boxtimes			
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Owner: Guzman Construction						
Name Signature				Date		

Additional Comments:

Operator: Altagracia "Lupita" Pena
Name

Guzman - Rosa Parks Stockpile Yard



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
North perimeter	Corrective Action	Repair or replace damaged silt fence	01-16-2025		
West perimeter	Maintenance	Repair or replace damaged silt fence	01-16-2025		
Kimmick	Maintenance	Repair or replace damaged silt fence	02-12-2025		
Rosa parks	Maintenance	Repair or replace damaged silt fence	02-26-2025		
Inlet inside silt fence near rosa parks	Maintenance	Inlet protection requires maintenance	11-20-2024		

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: John Paiz / 03-26-2025

Name Signature Date









