



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Fountain Hills Assisted Living				
Location:	4551 Vista Fuente Rd. NW				
Site Contact Name & Agency	Shawn Biazar - SBS <a href="mailto:aecllc@aol.com">aecllc@aol.com</a>	ESC File No.	C12E003B8		
		NPDES Id. No.	NMR1002DD		
Inspection Date:	05/06/20	Start/End Time:	1200/1215hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Earthwork				
Type of Inspection:	<input checked="" type="checkbox"/> regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	79*
Estimated date of last storm 0.25" or greater	4/13/2020		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed.		
	***Please provide latest SWPPPP nself-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 3/27/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 05/06/20