



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name and Location	FOUNTAIN HILLS ASSISTED LIVING, 4551 Vista Fuentes, NW		
Site Contact Name & Agency	Shawn Biazar, SBS Construction and Engineering, LLC, 505-804-5013	ESC File No.	DRN#C12E003B8
Date of Inspection	1-17-2020	Start/End Time	11:30 am and end 11:45 am
Inspector Name, COA Dept.			
Describe Present Phase of Construction	Pad over excavation has finished and need to get pad cleaned.		

Weather Information

Weather at time of this inspection? Clear	Temperature: ~ 32 F°
☐ Clear ☒ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snowing ☐ Windy Cloudy	
Has there been a storm event since the site was Permitted? ☐ Yes ☐ No No	
Amount: ☐ < 1/4" ☐ 1/4" to 3/4" ☐ > 3/4" ☐ Snow " ☐ < 1/4" to 3/4"	

Erosion & Sediment Control Inspection

Entrance / Track-Out	YES_ South Side of Property, SW corner
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	All The Silt Fence is installed
Inspection Reports Just working on the pad over excavation	
Erosion Controls	
Housekeeping/Pollutant Controls no dumpster is on site yet all the sign is posted	
Debris/Pollutants/Sediment in MS4 none	
Notes	

Is site being maintained in compliance with the Drainage Ordinance ? ☒ Yes ☐ No SHAWN BIAZAR 1-17-20
Signature Date

Overall Site Issues: Below are some general site issues that should be assessed during inspections.

BMP / Activity		Implemented?	Maintenance Required?	Corrective Action Needed and Notes
1	Are all slopes and disturbed areas not actively being worked, properly stabilized ?	qYes qNo	qYes qNo	no correction needed
2	Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs ?	qYes qNo	qYes qNo	not applicable
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	qYes qNo	qYes qNo	yes
4	Are discharge points and receiving waters free of any sediment deposits ?	qYes qNo	qYes qNo	yes
5	Are storm drain inlets properly protected ?	qYes qNo	qYes qNo	n/a
6	Is the construction exit preventing sediment from being tracked off-site, to the street?	qYes qNo	qYes qNo	yes
7	Is trash/litter from work areas collected and placed in covered dumpsters?	qYes qNo	qYes qNo	no, no construction on-site yet just dirt work
8	Are washout facilities (e.g., paint, stucco, conc.) available, clearly marked, and maintained?	qYes qNo	qYes qNo	no construction at this time
9	Are vehicle & equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	qYes qNo	qYes qNo	yes
10	Are materials that are potential stormwater contaminants stored inside or under cover?	qYes qNo	qYes qNo	no material on-site yet
11	Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?	qYes qNo	qYes qNo	Yes
12	Is site being maintained in compliance with Const. Gen. Permit ?	qYes qNo	qYes qNo	yes

Non-Compliance

Describe any incidents of non-compliance not documented above:

PRINT (Name and Title): Shawn Biazar, Managing Member

Signature: SHAWN BIAZAR **Date:** 1-17-20