



General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event
☐ Post-storm event

Weather Information

Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☒ **Clear** ☐ Cloudy ☐ Rain
☐ Sleet ☐ Snowing ☐ High Winds
☐ Partly Cloudy

Have any discharges occurred since the last inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

- ☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

- ☐ Yes ☒ No

If yes, where is it located?

Nearby gauge, NOAA, COCORHAS and Weather Underground monitored as secondary resources.

Has the Rain Event Page been filled out?

- ☒ Yes ☐ No



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Are there SDS sheets on site?

Yes

No

If yes, where are they located?

Inspectors log updated. SDS sheets on site with Site Super/ construction trailer; west side.

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

☐

Date Construction Resumed

☐

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Completed

Started:

08/20

Completed:

09/20

Site Clearing and Grading

Started

Started:

09/20

Completed:

10/20

Installing Utilities

Started

Started:

10/20

Completed:

☐



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Building Structure

Started

Started:

10/20

Completed:

☐

Paving and Walks

Started

Started:

03/21

Completed:

☐

Final Grading/Stabilize Site

Started:

☐

Completed:

☐

Other

Started:

☐

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Silt Fence, Curb Cut Back, Drop Inlet Protection, Security Fence, Stabilized Construction Entrance, Staging Area, Debris Containers, Watering.

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No



General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

If any of the controls have not been installed or require maintenance, please list the control and explain.

Fractured rock pad required at the east access point. Designated washout facility required. Repair / replace missing wire back silt fence along the north and west side. Street sweeping required at ROW. Replace 2' swale/ buffer along the east perimeter.

Are the BMPs shown on the map?

Yes

No

Were there any changes to the SWPPP?

Yes

No

Has the SWPPP been updated?

Yes

No

Were the changes to the SWPPP implemented within 7 days?

Yes

No

List any new BMPs needed:

No changes to the SWPPP document at this time. Sweeping required at construction access point. Designated washout facility. Repair / replace missing wire back silt fence along the north and west side. Replace 2' swale/ buffer along the east perimeter.

Notes:

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

Yes

No

N/A



General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Maintenance Required?

Yes	No	N/A
-----	----	-----

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

5. Are storm drain inlets properly protected?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----



General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required

Yes	No	N/A
-----	----	-----

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

12. Has the Site map been updated to reflect current conditions?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

13. Is the NOI posted?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes

No

Have there been any reportable quantities releases of hazardous materials?

Yes

No

Additional Notes

New Mexico Construction Stormwater Permit NMR10032L Effective Date: 7/15/2020 Expires: 2/28/2021 New Mexico Construction Stormwater Permit NMR10032M Effective Date: 7/15/2020 Expires: 2/28/2021

Certification & Signatures

Certification Statement:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Electronic Signature

X *Jeff Hart*

Date

April 20, 2021 at 12:37:49 PM MDT

Title
Senior Inspector



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	TLE @ Paseo and Eagle Ranch 4580 Nunzio Ave NW, Albuquerque, NM 87114	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event Sunday, February 14, 2021, 0.23"	Last Precipitation Sunday, April 18, 2021, 0.05" 48h Forecast 6% Chance of Rain

Weather History



Precipitation
Recorded




No
Precipitation



Missed or data
unavailable

April



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



INSPECTIONS PLUS

General Permit SWPPP Inspection

Site Name:	<u>TLE @ Paseo and Eagle Ranch</u> <u>4580 Nunzio Ave NW, Albuquerque, NM 87114</u>	Inspector:	Jeff Hart
Permit #:	NMR10032L NMR10032M	Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 20, 2021, 12:33:56 PM	Last Rain Event <u>Sunday, February 14, 2021, 0.23"</u>	Last Precipitation <u>Sunday, April 18, 2021, 0.05"</u> 48h Forecast <u>6% Chance of Rain</u>

There Are No Action Items