



TLE @ Paseo and Eagle Ranch  
Architectural Contractors, Inc.  
General Permit SWPPP Inspection

4580 NUNZIO AVE NW  
ALBUQUERQUE, NM 87114



Last Rain Event

Sunday, February 14, 2021, 0.23"

Last Precipitation

Friday, February 19, 2021, 0.02" --

48h Forecast

Inspection Date and Time  
Feb 23, 2021, 10:34:50 AM

Completed by  
Jeff Hart

Frequency  
Bi-weekly -

Permit #  
NMR10032L NMR10032M

Inspection Form Instructions - Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications - Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- Regular**
- ~~During storm-event~~
- ~~Post storm-event~~

Weather Information

Last Storm Event Information - For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- Clear**
- ~~Cloudy~~
- ~~Rain~~
- ~~Sleet~~
- ~~Snowing~~
- ~~High Winds~~
- ~~Partly-Cloudy~~

Have any discharges occurred since the last inspection?

- ~~Yes~~
- No**

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

~~Yes~~

| **No**

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

~~Yes~~

| **No**

If yes, where is it located?

Nearby gauge, NOAA, COCORHAS and Weather Underground monitored as secondary resources.

Has the Rain Event Page been filled out?

| **Yes**

~~No~~

Are there SDS sheets on site?

| **Yes**

~~No~~

If yes, where are they located?

Inspectors log updated. SDS sheets on site with Site Super/ construction trailer; west side.

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

---

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

~~Not Started~~

~~Started~~

| **Completed**

Started: 08/20

Completed: 09/20

Site Clearing and Grading

~~Not~~

~~Started~~

|

**Started**  
 ~~Completed~~

Started: 09/20

Completed: 10/20

Installing Utilities

~~Not~~  
 ~~Started~~

**Started**  
 ~~Completed~~

Started: 10/20

Completed:

Building Structure

~~Not~~  
 ~~Started~~

**Started**  
 ~~Completed~~

Started: 10/20

Completed:

Paving and Walks

Started:

Completed:

Final Grading/Stabilize Site

Started:

Completed:

Other

Started:

---

### Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Silt Fence, Curb Cut Back, Drop Inlet Protection, Security Fence, Stabilized Construction Entrance, Staging Area, Debris Containers, Watering.

Are all of the above controls installed?

**Yes**

~~No~~

Do any of the above controls need maintenance?

**Yes**

~~No~~

If any of the controls have not been installed or require maintenance, please list the control and explain.  
Fractured rock pad required at the east access point. Designated washout facility.

Are the BMPs shown on the map?

**Yes**

~~No~~

Were there any changes to the SWPPP?

~~Yes~~

**No**

Has the SWPPP been updated?

~~Yes~~

**No**

Were the changes to the SWPPP implemented within 7 days?

~~Yes~~

**No**

List any new BMPs needed:

No changes to the SWPPP document at this time. Sweeping required at construction access point. Designated washout facility. Wattles along SE fence base where silt fence is not trenched into the ground. Potential escapement to neighboring lot.

Notes:

Stockpiles require removal, watering or similar BMP.

---

## Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

**Yes**

~~No~~

~~N/A~~

Maintenance Required?

**Yes**

~~No~~

~~N/A~~

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or

similar BMPs?

Implemented?

~~Yes~~

~~No~~

| **N/A**

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

| **Yes**

~~No~~

~~N/A~~

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

5. Are storm drain inlets properly protected?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- Yes**
- ~~No~~
- ~~N/A~~

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- ~~Yes~~
- No**
- ~~N/A~~

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- Yes**
- ~~No~~
- ~~N/A~~

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required

- ~~Yes~~
  - No**
  - ~~N/A~~
-

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- ~~Yes~~
- No**
- ~~N/A~~

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- ~~Yes~~
- No**
- ~~N/A~~

12. Has the Site map been updated to reflect current conditions?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- ~~Yes~~
- No**
- ~~N/A~~

13. Is the NOI posted?

Implemented?

- Yes**
- ~~No~~
- ~~N/A~~

Maintenance Required?

- ~~Yes~~
- No**
- ~~N/A~~

14. Were previous corrections made within 7 days of last inspection or before the next storm

event?

Implemented?

~~Yes~~

**No**

~~N/A~~

Maintenance Required?

**Yes**

~~No~~

~~N/A~~

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

~~Yes~~

**No**

Have there been any reportable quantities releases of hazardous materials?

~~Yes~~

**No**

**Additional Notes**

New Mexico Construction Stormwater Permit NMR10032L Effective Date: 7/15/2020 Expires: 2/28/2021 New Mexico Construction Stormwater Permit NMR10032M Effective Date: 7/15/2020 Expires: 2/28/2021



## Certification

### Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

### Electronic Signature

**X** *Jeff Hart*

Date

February 23, 2021 at 10:39:43 AM MST

Title

Senior Inspector

---

## Photos

Description



*Photo 1*

1536727 bytes

Location Description

SW corner.

---

Description



*Photo 1*

2670658 bytes

Location Description


SE corner at security fence base.

---

## Weather History

Precipitation Recorded  No Precipitation  Missed or data unavailable

### February



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.

There Are No Action Items