



# INSPECTIONS PLUS

## TLE @ Paseo and Eagle Ranch

Architectural Contractors, Inc.

Weather Event Inspection



4580 NUNZIO AVE NW  
ALBUQUERQUE, NM  
87114



Last Rain Event

Tuesday, October 27, 2020,  
0.23"

Last Precipitation

Wednesday, October 28, 2020,  
0.06"

48h Forecast

54% Chance of  
Rain

Inspection Date and Time

Oct 27, 2020, 5:15:19 PM

Completed by

Jeff Hart

Frequency

Permit #

NMR10032L NMR10032M

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

### a. Site Inspection

1. Are there any erosion control structures damaged from the rain event?

~~Yes~~

| **No**

Notes:

N/A

2. Are there signs of new ruts or gullies from the rain event?

~~Yes~~

| **No**

Notes:

N/A

3. Are there signs of significant amounts of mud in the street or outfalls from the rainfall event?

~~Yes~~

| **No**

Notes:

N/A No active work.

4. Are there any conditions that need immediate attention?

~~Yes~~

| **No**

Notes:

N/A

Part 2: Inspection report summary.

## b. Inspection Report Summary

### 1. Qualifications of Inspector:

Training and work experience – see inspector qualification page in the SWPPP.

### 2. Measures/Areas Inspected:

Site perimeter, no active work.

### 3. Observed Conditions:

### 4. Changes Necessary to the SWPPP:

### 5. Were there any discharges?

Notes:

### 6. What did the water look like at the time of the discharge?

Notes:

### 7. Was Inspection Conducted Within 24 Hours of Last Rainfall Over 1/4"?

Notes:

### 8. How much did it rain?

Reference precipitation values included with this form.

Notes:

Best Management Practices are in place. Site remains clean and organized.

## Certification

### Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

### Electronic Signature

**X** *Jeff Hart*

Date

October 28, 2020 at 10:52:18 AM MDT

Title

Senior Inspector

---

## Action Items

Title	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Imgs
Sediment and Erosion Control Management	Jeff Hart	September 22, 2020	7 Days	Construction access point (s)	Install Fractured Rock Access pad, as soon as feasible, as required by the Erosion Control Plan.	Closed September 28, 2020	Jeff Hart	✓ Closed September 28, 2020Fractured rock access pad installed. Complete.	