

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation				
ESC File No.	C12E	004 Pr	roject Name:		Kiddie Aca	demy Westside		
NPDES Id. No.	NMR10	00370 Lo	ocation:		4590 Para	adise Blvd. NW		
12/	2/2021	Owner			Contractor			
Operator		Azaan Holdings			Snyder Construction			
Contact na	me & title	Aleem Hasham			Benny Saiz			
e-mail			n@kiddieacade	my.net		er-const.com		
Contact Phone #		501-256-9687			505-263-0961			
COA Inspector		Doug Hughes			Start/End Time			
	ction Phase:	Buildi	ng occupied, onsi	te finished, c	ffsite not stabi	lized, trailer still	onsite.	
Type of Ir	nspection:	Follow-up	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of i		inspection?	clea	r	Tempe	rature: ~	45	
Estimated	date of last s	storm 0.25" or	greater		10/1/2021			
Item			Deficienc	cy/ Correcti	ve Action			
Number								
1	Permit covera	ge <u>not posted</u> f	or safe public vie	wing.				
2	SWPPP was not up-to-date. The SWPPP map did not show current BMPs. The Operator's signature was							
	missing from thye SWPPP and the inspection reports. The deligation to Snyder doesn't meet the						et the	
	requirements	of Appendix I (r	no third party del	igations) and	the deligation	wasn't signed by	the Operator	
					_	,	•	
4	(Snyder signed it). Add operator signatures and up-date the map. Final stabilization per CGP2.2.14.b required to terminate permit coverage. Continue inspections and						tions and	
· ·		•	c 1012 Native see		_	•		
					-		illai	
	Stabilization St	o permit covera	ige and inspection	ns can be ter	minated prom	ouy.		
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports		Latest re	port Date:	11/4/2	2021	

The SWPPP will be kept inside the building in the office to the left of the entrance. Inspection frequency can be reduced to once a month if cover satisfies 2.2.14.a.	Notes: Onsite stabilized, offsite has seed and mulch recently applied.
Inspection frequency can be reduced to once a month if cover satisfies 2.2.14.a.	The SWPPP will be kept inside the building in the office to the left of the entrance.
	Inspection frequency can be reduced to once a month if cover satisfies 2.2.14.a.
Cover sediment, posting and SWPPP to be monitored by inspections.	 Cover sediment, posting and SWPPP to be monitored by inspections.

City of Albuquerque Stormwater Inspector Signature and date: 12/06/2021

Contact information: Doug Hughes 505-924-3420

jhughes@cabq.gov

James D. Hughes