

### INSPECTION REPORT

## GENERAL INFORMATION

DATE OF INSPECTION:	6/1/2021
COMPANY NAME:	Snyder Construction
PROJECT NAME:	Kiddie Academy Westside Project #19-0065
LOCATION:	4590 Paradise Blvd, Albuquerque, New Mexico, 87114
TRACKING NO:	NMR1002X1
COMPLIANCE EVALUATION:	Marginal
TYPE OF INSPECTION:	Rain Event
START TIME:	12:00 PM
END TIME:	12:20 PM
INSPECTOR'S NAME:	Gaylen Barnett
INSPECTOR'S TITLE:	Environmental Compliance Manager
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person
INSPECTOR'S CONTACT:	505-620-2036
PHASE OF CONSTRUCTION:	<ul><li>Clear and Grub ☐ Excavation ☑ Building (vertical)</li><li>Rough Grading ☐ Infrastructure ☐ Final Grading</li><li>Final Stabilization</li></ul>
IF RAIN EVENT HOW WAS RAINFALL AMOUNT DETERMINED:	Rain Gauge Other Cocorhas website

### WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?

Yes

○ No

IF YES, PROVIDE:

Rain and Thunderstorm

#	STORM DATE	ESTIMATED STORM DURATION (HOURS)	APPROXIMATE PRECIPITATION (INCHES)	-
1	5/31/2021	4	0.50	

WEATHER AT TIME OF THIS INSPECTION:

Clear

TEMPERATURE:	78	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	○ Yes	● No
ARE ANY DISCHARGES OCCURRING NOW?	○ Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	○ Yes	● No

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	Wattles/Socks/Lo g Roll	None	Initial Install	Add wattle or silt fence to NE corner of project	1	EA	

## GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	○Yes	
2	Are steep slope areas not actively being worked properly stabilized?	●Yes ○No ○N/A	○Yes	
3	Are disturbed areas not actively being worked properly stabilized?	Yes No N/A	○Yes	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	● Yes ○ No ○ N/A	○Yes ● No	
5	Are discharge points and receiving waters free of any sediment deposits?	● Yes ○ No ○ N/A	○Yes ● No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	○ Yes ● No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	●Yes ○No ○N/A	○ Yes	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	○ Yes   No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	●Yes ○No ○N/A	○ Yes	
10	Are offsite flows entering the construction site?	○Yes ● No ○N/A	○ Yes ● No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○Yes ● No ○N/A	○Yes	See above comment about wattles in NE site corner. This is a potential discharge location.
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	● Yes ○ No ○ N/A	○ Yes  No	
13	Are non-stormwater discharges properly controlled?	● Yes ○ No ○ N/A	○ Yes	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	● Yes ○ No ○ N/A	Yes No	
15	Are changes to the SWPPP necessary at this time?	Yes ● No N/A	○Yes ● No	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	○Yes ● No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	○Yes	This inspection was performed by Sam Stribling.

### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:

Gaylen Barnett

DATE:

June 02, 2021

SIGNATURE AND AFFILIATION:

Regenement

#### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:

DATE: