

- STANFORD STANFORD	General Information
Project Name and Location	General Information  Smiles for Kids  PON and Eagl Rench  505
Site Contact Name & Agency	Dave Bown Contact Phone # 566 - 8412
Date of Inspection	3-22-16 Time 1/:30/
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	Stephitzer
Type of Inspection:	
Regular • During sto	rm event • Post-storm event • 311 / Complaint Response • Follow-Up
	Weather Information
Weather at time of this inspec	tion? Temperature: ~65
Char · Cloudy ·	Rain · Sleet · Fog · Snowing · windy
Has there been a storm event	since the site was Permitted? · Yes · No
Amount: • < 1/4" (1/4" t)	3/4" • > 3/4" • Snow
	Erosion & Sediment Control Inspection
Check any BMPs that	nave FAILED or REQUIRE MAINTENANCE
Entrance / Off Tracking	~/A
<ul> <li>Sediment Controls / Sill</li> <li>Check Dams, Waddl</li> </ul>	es, etc. No since
Erosion Controls / Mule	
• Wind Blown Erosion	
■ Debris/Pollutants/Sedin	ment in MS4
	3-22-4
Is site being maintained in comp	liance with the Drainage Ordinance? No Signature Date

From: Sent: Dave Brown <dave@insightnm.com> Monday, January 25, 2016 5:42 PM

To:

Cherne, Curtis

Cc:

'iohn.rescate@insightnm.com'; grant@inspectionsplusinc.com

Subject:

RE: Smiles for Kids SWPPP inspection

Curtis.

Thanks for the information,

We needed to take down the old silt Fence do to it retaining 18 inches of dirt. We needed to for landscaping. We are hiring American Fence to reinstall the mesh type Fence in its place.

We will be installing it on the west side property, West side along our new drive and along the to two busy streets.

I believe this will be taking place Wednesday or Thursday.

Call if you have any questions 506 8412

Thanks

Dave Brown

Sent from my Verizon Wireless 4G LTE smartphone

----- Original message -----

From: "Cherne, Curtis" < CCherne@cabq.gov>

Date: 1/25/2016 2:42 PM (GMT-07:00)

To: "'dave@insightnm.com'" < dave@insightnm.com>

Cc: "'john.rescate@insightnm.com'" < john.rescate@insightnm.com >, grant@inspectionsplusinc.com

Subject: Smiles for Kids SWPPP inspection

Dave,

I visited the Smiles for Kids at PDN and Eagle Ranch on January 13<sup>th</sup> then again on January 22<sup>nd</sup>.

On the 13<sup>th</sup>, (first two photos) TLC was doing a utility cut in Eagle Ranch and the drive into the bldg was getting prepped for paving. TLC told me they would sweep Eagle Ranch and I stopped by and talked to John about cleaning up Loma Fuente. Before I finished my report, John had two guys out manually sweeping Loma Fuente. Very Good and I appreciate John's efforts.

I had to return to the area on the 22<sup>nd</sup> as the project up the street was not doing so well.

Loma Fuente Rd. looked good, however;

NPDES Tracking No: NMR12 3/67

ECS File: 69 6009 6009



N EL MAN					
	General Information				
Project Name	Smitus for Fulls				
and Location	PAN and Eagle Reveh				
Site Contact Name & Agency	Smiter for Foll PAN art Bagh Rech Dave Brims Insight construction	Contact Phone #			
Date of Inspection	1-22-16	Start/End Pill 9220			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	nspector Qualifications Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	blds unstructer, paring 1	rku			
Type of Inspection:					
Regular • During stor	rm event • Post-storm event • 311 / Com	plaint Response • Follow-Up			
	Weather Information				
Weather at time of this inspect	ion? Rain · Sleet · Fog · Snowing ·	Temperature: ~F° Windy			
Has there been a storm event si Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? • Yes • No  '4" • > 34" • Snow"				
	Erosion & Sediment Control Inspec	ction			
Check any BMPs that ha	ave FAILED or REQUIRE MAINTENANCE				
<ul> <li>Entrance / Off Tracking</li> </ul>	ok				
<ul> <li>Sediment Controls / Silt F</li> <li>Check Dams, Waddles</li> </ul>		Eagh Fast Pe			
Erosion Controls / Mulch	, Seed,				
<ul> <li>Wind Blown Erosion _</li> </ul>	NO				
<ul> <li>Housekeeping / Pollutant</li> </ul>	Controls				
Is site being maintained in complian	nce with Const. Gen. Permit ?" Yes No Si	nt a chr 1-22-4 ignature Date			

From:

Cherne, Curtis

Sent:

Monday, January 25, 2016 2:42 PM

To:

'dave@insightnm.com'

Cc:

'john.rescate@insightnm.com'; grant@inspectionsplusinc.com

Subject:

Smiles for Kids SWPPP inspection

Attachments:

messy-temp-access-.jpg; sediment-fuente2-.jpg; no-silt-fence-.jpg; sediment-eagle-ranch-.jpg;

silt-fence-maintenance-.jpg

#### Dave,

I visited the Smiles for Kids at PDN and Eagle Ranch on January 13<sup>th</sup> then again on January 22<sup>nd</sup>. On the 13<sup>th</sup>, (first two photos) TLC was doing a utility cut in Eagle Ranch and the drive into the bldg was getting prepped for paving. TLC told me they would sweep Eagle Ranch and I stopped by and talked to John about cleaning up Loma Fuente. Before I finished my report, John had two guys out manually sweeping Loma Fuente. Very Good and I appreciate John's efforts.

I had to return to the area on the 22<sup>nd</sup> as the project up the street was not doing so well. Loma Fuente Rd. looked good, however;

- 1. The silt fence that was taken down on the 13<sup>th</sup> was not replaced on the 22<sup>nd</sup>.
- 2. Either the site silt fence was completely removed along Eagle Ranch or requires maintenance. (There was two silt fences earlier in the project.)
- 3. The sediment in Eagle Ranch is present quite far downhill from the site.

I would like these issues addressed.

Thanks.

Curtis Cherne, P.E. Stormwater Quality, COA 924-3420



You are here: Permits Landing Page 2012 CGP 2012 CGP Details

# 2012 Construction General Permit eNOI Detail

Quick Jump to Other **Permits** 

#### Details for NMR12B917

#### **General Information**

Project / Site Name: Current Status: Tracking Number: Permit Type:

Smiles for Kids Dental Off Submitted To EPA NMR12B917 NOI

#### **Interview Page Answers**

Is your project/site located in Indian Country Lands? Are you requesting coverage under this NOI as a 'federal operator' as defined in Appendix A?

No

#### Operator Information

Operator's Name: Street: City: State: Zip Code: Point of Contact Name: Phone Number: Operator Email: Fax: IRS Employer Identification Number (EIN): Insight Construction PO Box 6653 **Albuquerque** New Mexico 87197 David Brown (505) 888-7927 dave@insightnm.com N/A

#### Project / Facility Information

Project / Site Name: Street: City: State: Zip Code:

Project / Facility on Indian Land?

Reservation Name:

Smiles for Kids Dental Off 9201 Eagle Ranch Rd NW Albuquerque

New Mexico 87114 No N/A

N/A

#### **Additional Project Information**

Feedback

NPDES Tracking No: NMR12 8917

ECS File: (125059



		200	
	General Information		
Project Name and Location	Smits for Kids  PDN av Eigh Pock  John Rescate  Finsight construction		
Site Contact Name & Agency	John Rescate Fosight Construction	Contact Phone #	934-9196
Date of Inspection	11-20-15	Start/End 71	30/q:rs
Inspector Name, COA Dept.	Curtis Cherne,	Stormwater Quality	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormw	ater- Stormwater One	
Describe Present Phase of Construction	Bldg vertical, prof grate	d	
Type of Inspection:  Regular During sto	rm event • Post-storm event • 311 / Co	omplaint Response •	Follow-Up
	Weather Information		
	Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes · No	• Windy	perature: ~_ <u>\$</u> 6
Amount: · < 4/4			
	Erosion & Sediment Control Insp	ection	
	Entrace Mil Mantan M		-ot
<ul> <li>Sediment Controls / Silt I Check Dams, Waddles</li> </ul>	· • • • • • • • • • • • • • • • • • • •	·····	
<ul> <li>Erosion Controls / Mulch</li> </ul>	, Seed, <b>\(\begin{array}{c} \bigs\)</b>		
• Wind Blown Erosion	<b>№</b> 0	1 ,	
Housekeeping / Pollutant		fixen's Solt of	Co while & Ken
· Spok W/	John site supr, Skey were		MC3 .
Is site being maintained in complia	nce with Const. Gen. Permit ? Yes	Signature	1/- 20-11 Date

NPDES Tracking No: NMR12 8917

ECS File: 425059



	General Information			
Project Name and Location	Smiles for Kill PDN and Eagle R	and	1	
Site Contact Name & Agency	PDN and Eagle R July Rescale Insight construction	Contact Phone #	101- 4/96	
Date of Inspection	1-13-16	Start/End /1	20/ 2:02	
Inspector Name, COA Dept.	Curtis Cherne, Sto		/	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	spector Qualifications Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction Type of Inspection:	Fire graded, prepping endrance	PZ, UZ/1h	cut in Caple Pu	
Regular During stor	rm event • Post-storm event • 311 / Comp	plaint Response	Follow-Up	
	Weather Information			
	Rain · Sleet · Fog · Snowing · Vince the site was Permitted? · Yes · No	Tem Windy	perature: ~ 9° F°	
	Erosion & Sediment Control Inspect	tion		
<ul> <li>Check any BMPs that have</li> <li>Entrance / Off Tracking</li> <li>Sediment Controls / Silt For Check Dams, Waddles</li> </ul>	1 .	Stobilital en Rd - 4/5 o	trane t subs	
<ul> <li>Erosion Controls / Mulch</li> </ul>	Seed, ~1			
• Wind Blown Erosion				
<ul> <li>Housekeeping / Pollutant</li> </ul>	Controls 011			
· Spoke to Supr	sais he would sweep A	sm -he	was I left	
Is site being maintained in complian	nce with Const. Gen. Permit ?* Yes * No Sig	to 6 cm	1-B~1 \} Date	

# CITY OF ALBUQUERQUE

July 22, 2015



David Brown General Superintendent Insight Construction P.O. Box 6653 Albuquerque, NM 87197 dave@insightnm.com

Re: Lack of eNOI filing with the EPA

Dear Mr. Brown,

On July 1<sup>st</sup>, 2015 you were informed that you needed to file an eNOI with the EPA for your construction activities at 9201 Eagle Ranch Rd NW. We spoke shortly after that and you confirmed that you would file with the EPA.

The filing status was checked this morning and it appears you still haven't filed with the EPA.

You are to provide an NPDES Tracking number within two weeks or your non-compliance will be reported to the New Mexico Environment Department, Surface Water Quality Bureau to aid in the determination if this issue is to be forwarded to the EPA. The NPDES Tracking Number should be emailed to ccherne@cabq.gov

PO Box 1293

If you have any questions, you can contact me at 924-3420.

Albuquerque

New Mexico 87103

www.cabq.gov

Sincerely,

Curtis Cherne, P.E.

Cute a chem

Principal Engineer, Stormwater Quality

Planning Dept.

C: email

From:

Cherne, Curtis

Sent:

Thursday, July 30, 2015 3:09 PM dave@insightnm.com tim@superiorstormwater.com Receipt of eNOI

To:

Cc:

Subject:

Dave,

I am in receipt of your CGP eNOI Tracking Number NMR12B917. This fulfills the requirement set forth in the letter dated 7-22-15.

Curtis



	General Information			
Project Name and Location	Smikes for Kids Eagle Reach a PON	ESC PERM	IT#	
Site Contact Name & Agency	Eagle Rouch a PDN  Damian Chamerti  Insight Construction			505-600-7927
Date of Inspection	6-15-13	Start/End Time	10:	40/10:55
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Stormwater USA			
Describe Present Phase of Construction	rough grobe, forming Bld	9 wall		
Type of Inspection: Regular Prive-By/Random During storm event Post-storm event 311 / Complaint Response Follow-Up				
	Weather Information			
Has there been a storm event s	Rain · Sleet · Fog · Snowing · ince the site was Permitted? · Yes · No		• Ot	
Amount: • < 1/4" • 1/4" to 3	4" · > ¾" Intensity: · Light · M			• Snow
Erosion & Sediment Control Inspection  Check any BMPs that have FAILED or REQUIRE MAINTENANCE  Entrance / Off Tracking  Grand Grand Grand  Sediment Controls / Silt Fence,  Silt has 511t force, however the are gapt				
Erosion Controls / Mulch, Seed,  Sediment Controls / Silt Fence,  Check Dams, Waddles, etc.  Orry when it wasn't to the in hers  Fagle fand, 5:11 fence full  and burkel				
• Wind Blown Erosion				
Housekeeping / Pollutant Controls  Spok w/ Danian Control mtgathi  Is site being maintained in compliance with Const. Gen. Permit? Yes O work of C-15-15  Signature Date				

From:

Cherne, Curtis

Sent:

Wednesday, July 01, 2015 4:34 PM

To: Subject: 'dave@insightnm.com' smiles for kids eNOI

Dave,

Good afternoon.

I checked the EPA website for your eNOI submittal and did not see it.

I checked under Smiles for Kids and zip codes 87114 and 87120.

If I missed it, let me know your tracking number, else you need to submit as you have already started.

Curtis Cherne, PE Stormwater Quality Engineer 924-3420

call Das Brun 7-27-15