

## City of Albuquerque Stormwater Construction Site Inspection Report

N. W.	MEX							
			General In	formation				
Project Name:		Smiles for Kids						
Location:		9201Eagle Ranch Rd and 9211 and Tr F & G Fountain Hills Plaza						
Site Contact Name &		Jim Tasker-TH	R Properties, LLC	ESC File No.		C12E054-C12E054B		
Agency		stasker@pedi	atric.dental.com	NPDES Id. No.		NMR 100089		
Inspection Date:			tart/End Time: 11					
	water Inspecto		imothy E. Sims					
Constru	ction Phase:		•					
Type of Ir	spection:	Regular	Storm Event	Post Storm Ev	/ent >0.25"	311/Complaint x Follow Up		
Weath	er at time of i	nspection?	Clea	r	Tempe	erature: ~ 82		
Estimated	date of last s	torm 0.25" o	r greater			4/13/2020		
Item								
	Deficiency/ Corrective Action							
Number				•				
	All previous is	sues mitigated	, no new issues ol	oserved with t	his inspecti	on		
					•			
	1							
	***Please pro	vide latest SW	PPP self-inspectio	n report.				
	inspection rep	orts will need	continuing submi <sup>,</sup>	ttal to Stormw	ater Qualit	y until site stabilization is		
	completed.							
	oop.etear							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspec	tion Reports	requested	Latest repo	ort Date:	5/11/2020		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155