



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C13E028	Project Name:	Circle K
NPDES Id. No.	NMR1006HJ/NMR1006H5	Location:	9610 Eagle Ranch Rd NW
8/2/2024	Owner	Owner	
Operator	Circle K Stores Inc.	RS Eagle Ranch, LLC	
Contact name & title	Mark Tate	Kevin Mattson	
e-mail	zmurphy@circlek.com	kmattson@redskyholdings.com	
Contact Phone #	303-903-1116	972-369-4123	
COA Inspector	Chancellor English	Start/End Time:	11am
Construction Phase:	grading		
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear	Temperature: ~	90
Estimated date of last storm 0.25" or greater	6/30/2024		

Item Number	Deficiency/ Corrective Action		
1	The SWPPP is not certified by Circle K Stores Inc. in violation of CGP Part 7.2.10. Required mitigation: Your signatory must sign and date your SWPPP in accordance with CGP Appendix G, Part G.11.		
2	There is sediment track-out on Irving Blvd coming from vehicles not using the stabilized construction entrance on Eagle Ranch Rd in violation of CGP Part 2.2.4. There is also sediment deposited onto a neighboring property from a failure at the silt fence at the southern corner of your property. Required mitigation: Restrict vehicle use to properly designated exit points and where sediment has been tracked-out from your site onto paved roads, sidewalks, or other paved areas outside of your site, remove the deposited sediment by the end of the same business day in which the track-out occurs. Remove the track-out by sweeping, shoveling, or vacuuming these surfaces. You are prohibited from hosing or sweeping tracked-out sediment into any constructed or natural site drainage feature, storm drain inlet or receiving water per CGP Part 2.2.4.		
3	The permit coverage posting was missing in violation of CGP Part 1.5. Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site. The notice must be located so it is visible from the public road that is nearest to the active part of the construction site per CGP Part 1.5.		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	no	Latest report Date: N/A

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 8/8/2024
Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov

Chancellor English