



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C13E028	Project Name:	Circle K
NPDES Id. No.	NMR1006HJ/NMR1006H5	Location:	9610 Eagle Ranch Rd NW
8/2/2024	Owner	Owner	
Operator	Circle K Stores Inc.	RS Eagle Ranch, LLC	
Contact name & title	Mark Tate	Kevin Mattson	
e-mail	zmurphy@circlek.com	kmattson@redskyholdings.com	
Contact Phone #	303-903-1116	972-369-4123	
COA Inspector	Chancellor English	Start/End Time:	315pm
Construction Phase:	Utilities		
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input type="checkbox"/> Follow Up
Weather at time of inspection?	Clear	Temperature: ~	55
Estimated date of last storm 0.25" or greater	11/7/2024		
Item Number	Deficiency/ Corrective Action		
1	None		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Yes	Latest report Date: 11/27/2024

Notes:

SWPPP was in construction trailer at entrance of site. Access to entrance is through the Mango Automotive Parking Lot.

City of Albuquerque Stormwater Inspector Signature and date: 12/6/2024
Contact information: Chancellor English (505) 924-3325
english@cabq.gov

Chancellor English