



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

ESC File No.	C17E002A33	Project Name:	98th and Central Warehouse		
NPDES Id. No.	NMRI006VD	Location:	9561 Central Ave NW		
4/3/2025	Owner	Contractor			
Operator	SkinJam, LLC	Mechenbier Construction, Inc.			
Contact name & title	Michaela Jacobs	Jeremy Mechenbier			
e-mail	<a href="mailto:jacobs@riograndedermatology.com">jacobs@riograndedermatology.com</a>	<a href="mailto:jeremymechenbier@mechenbier.com">jeremymechenbier@mechenbier.com</a>			
Contact Phone #	505-896-2900	505-314-7700			
COA Inspector	Chancellor English	Start/End Time:	12:30pm		
Construction Phase:	verticals				
Type of Inspection:	<b>Regular</b>	Storm Event	Post Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?	Clear	Temperature:	~	55	
Estimated date of last storm 0.25" or greater		11/7/2024			
Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	3/31/2025	

Notes:	
Check the silt fence after recent high winds.	

City of Albuquerque Stormwater Inspector Signature and date: 4/4/2025  
Contact information: Chancellor English (505) 924-3325  
[cenglish@cabq.gov](mailto:cenglish@cabq.gov)

Chancellor English