**City of Albuquerque Stormwater Construction Site Inspection Report**

## General Information

| | | | |
|---|---|---|---|
| ESC File No. | C17E002A33 | Project Name: | 98th and Central Warehouse |
| NPDES Id. No. | NMR1006VD | Location: | 9561 Central Ave NW |

| 8/13/2025 | Owner | Contractor |
|---|---|---|
| Operator | SkinJam, LLC | Mechenbier Construction, Inc. |
| Contact name & title | Michaela Jacobs | Jeremy Mechenbier |
| e-mail | jacobs@riograndedermatology.com | jeremymechenbier@mechenbier.com |
| Contact Phone # | 505-896-2900 | 505-314-7700 |

| **COA Inspector** | **Chancellor English** | Start/End Time: | 10am |
|---|---|---|---|
| Construction Phase: | Interiors | | |

| Type of Inspection: | Regular | Storm Event | Post Storm Event >0.25" | 311/Complaint | Follow Up |
|---|---|---|---|---|---|

| Weather at time of inspection? | Clear | Temperature: ~ | 80 |
|---|---|---|---|
| Estimated date of last storm 0.25" or greater | | 7/3/2025 | |

| Item Number | Deficiency/ Corrective Action | | | |
|---|---|---|---|---|
| 1 | None | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 2.1 | Discharge off site? (Y/N) | no | | |
| 4 | Self Inspection Reports | Yes | Latest report Date: | 8/4/2025 |

| Notes: | |
|---|---|
| | |
| | |
| | |
| | |

City of Albuquerque Stormwater Inspector Signature and date: 8/13/2025

Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov

Chancellor English