

			General Information			
Project Name and Location		PDN	Spurts Compley			
		PDA	v + washington			
Site Contact Name & Agency		Randy Mexico A	Sports Compley V 4 washington Case ESC File No. NPDES ID No. Start/End Start/End			
Date of Inspection		12-17	-18 Start/End 11: 10/			
COA Inspector Name		Curtis Cherne, Stormwater Quality				
Describe Present Phase of Construction		5 Lah. 11218				
Type of In	nspection: lar • During storn	m event • Post	t-storm event (> 0.25 inch) • 311 / Complaint Response • Follow-Up			
			Weather Information			
	at time of this inspection		Temperature: ~ <u>45</u> F° • Fog • Snowing • Windy			
l	• been a storm event sin		Permitted? Yes No Snow"			
			Inspection			
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes			
1.5	Post a Notice					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter		V			
2.2.4	Minimize sediment track	-				

2.2.5	Manage stockpiles			14.	
2.2.6	Minimize Dust				
2.2.10	Protect Storm Drain Inlets				
2.2.10	Protect Storm Drain Inlets				
2.2.11	Minimize erosion of conveyance channels				
2.2.12	Sediment Basins				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.			Stabilizal	
2.3.1	Equipment and Vehicle Fueling				
2.3.2	Equipment and Vehicle Washing				
2.3.3	Building Material Storage				
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage				
2.3.3	Construction and Domestic Wastes				
2.3.3	Construction and Domestic Wastes				
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		A		
2.4	Dewatering				
2.1	Discharge off site?	· Yes · No			
4	Self-Inspection Reports	ı	Lates	Report Date:	
¹ Constru	ty Inspector Use) Items in ction General Permit (C nce or corrective action	CGP)			
Notes:					
				Advantable	
					
City	of Albuquerque Storm	water Inspecto	or Signa	ture and Date: Curtor a Chen	<u>e</u> 12-12-12 Date

 $Contact\ Info:\ Curtis\ Cherne, 505-924-3420,\ ccherne@cabq.gov$

ECS File: C17 Eoug



	General Information					
Project Name	PDN Sportsplex					
and Location	PDN Sportsplex PDN 4 washington					
Site Contact Name & Agency	Rendy Case Mexico Nuevo Combocoho	Contact Phone #/ E-mail	505 975-1317			
Date of Inspection	6-14-17	Start/End //	10/			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One					
Describe Present Phase of Construction	Vertra stul constructed					
Type of Inspection: Regular • During store	rm event • Post-storm event (> 0.5 inch)	· 311 / Complaint Resp	onse • Follow-Up			
	Weather Information					
Weather at time of this inspect	ion?	Tem	perature: ~ 85 F°			
	Rain • Sleet • Fog • Snowing					
Has there been a storm events: Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? Yes No 4" > 34" Snow					
	Erosion & Sediment Control Ins	pection				
 Entrance / Track-Out 	Courd we mainten in	new fuhre-	NU bucho			
 Sediment Controls / Silt F Check Dams, Waddles 	•					
Erosion Controls / Mulch, Seed,						
* Housekeeping/Pollutant Controls Oll - Why Wan - has mash out roll-off						
Debris/Pollutants/Sediment in MS4						
· Notes Consider	w heath - Now sile	has si	<u>in</u>			
NMPI'S	31294		,			
Is site being maintained in complian	nce with the Drainage Ordinance ? • Yes • No	Cuto a M	6-14-17 Date			

ECS File: C17 EUU



		General Information			
	0.0				
Project Name	PDN	Sportsplay			
and Location	PDN and washington				
	0 1	(.0		Sos	
Site Contact Name & Agency	Randy Care		Contact Phone #/ E-mail	505 975-1317	
	Mexico No	elevo Cuntactador		975-1317	
Date of Inspection	2-6-1		Start/End Time	1:20/11:35	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccl	nerne@cabq.gov			
Inspector Qualifications	Qualified Comp	liance Inspector of Stormwate	er- Stormwater One		
Describe Present Phase of Construction	DOUMAG	foundation			
Type of Inspection:	pooring	y out of your			
Regular During stor	rm event • Post	-storm event (> 0.5 inch) 3	11 / Complaint Resp	onse • Follow-Up	
		Weather Information			
Weather at time of this inspect	ion?		Tem	perature: ~ 56 F°	
· Clear / Cloudy		· Fog · Snowing	Windy	_	
Has there been a storm event s		Permitted? · Yes) · No			
Amount: • < 1/4" to 3	3/4'' > 3/4''	• Snow"			
	Erosion	& Sediment Control Inspec	tion		
Entrance / Track-Out	ok				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.					
Erosion Controls / Mulch, Seed,					
Housekeeping/Pollutant Controls has a hish-out bin at 15 Using id					
• Debris/Pollutants/Sediment in MS4					
• Notes					
Is site being maintained in complian	nce with the Drainage		Centra. C		
		U Si	gnature	Date	

ECS File: C17 Boch



	General Information				
Project Name and Location	PON sports plex randy & randy & pon and wishington mx numo. com				
Site Contact Name & Agency	Randy Case Contact Phone #/ 505 Moxico Neuro Contradator Contact Phone #/ 915-1317				
Date of Inspection	11-9-16 Start/End 1:00/1-20				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction Type of Inspection:					
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up				
	Weather Information				
	Rain · Sleet · Fog · Snowing · Windy Since the site was Permitted? · Yes · No				
Amount: • < 1/4" • 1/4" to 3					
	Erosion & Sediment Control Inspection				
■ Entrance / Track-Out	ok				
 Sediment Controls / Silt I Check Dams, Waddles 					
Erosion Controls / Mulch	, Seed, No				
 Housekeeping/Pollutant (Controls OK				
 Debris/Pollutants/Sedime 	ent in MS4				
· Notes Fraklin	in-orderis				
Is site being maintained in complian	nce with the Drainage Ordinance? • (Ye) • No Late • Chu 11 9-14 Date				

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Wednesday, November 09, 2016 3:15 PM

To:

'randy@mxnuevo.com'

Subject:

Sportsplex at PDN SWPPP inspection

Randy,

Good afternoon.

I stopped by the your Sportsplex site on Paseo del Norte today.

The site overall looked good. Most of it is lower than adjacent grade so I don't see a problem for not having silt fence/filter socks. It looked like the site will drain into the waterline trench and a pond at the southwest corner. When site conditions change, silt fence/filter sock may be needed on the west side.

I noticed your address is in Corrales so you may not be familiar with the requirement to have an approved Erosion and Sediment Control Plan and Erosion and Sediment Control Permit for the earth disturbance. It would be good to see a plan within 30 days. I see that Tim with Superior prepared your SWPPP. They also prepare Erosion and Sediment control plans which most likely will look a lot like the site map in the SWPPP.

NO NAPORO 11-16-16

If you have any questions, please let me know.

Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA

COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."