

General Permit SWPPP Inspection						
Site Name:	<u>Horizon Village</u> <u>Horizon Village</u>	Inspector:	Greg Cimine	ra		
Permit #:	NMR10023D and NMR10023E C17E119	Inspection Frequency:	Bi-weekly			
Date of Visit:	Apr 27, 2022, 7:58:18 AM	Last Rain Event Thursday, March 24, 2022, 0.0"	Last Precipitation Saturday, April 2, 2022, 0.04"	48h Forecast 1% Chance of Rain		

**Inspection Form Instructions** 

Review each question for this inspection carefully, then answer YES, NO, or N/A (no compliance, press the "Add Action Item" button above to add a corrective action.	ot applicable). If any of the items below are out of
General Information	
<u>Inspector's Qualifications</u> Trained and work experience - see inspector qualification page in section 2 of the S	SWPPP.
Type of Inspection:	Regular During storm event
	Post-storm event
Weather Information	
<u>Last Storm Event Information</u> For information on the last storm event, see the weather event information at the	end of this inspection.
Weather at time of this inspection?	Clear Cloudy Rain
	Sleet Snowing High Winds
	Partly Cloudy
Have any discharges occurred since the last inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	Clear Partly Turbid Very Turbid
Are there any discharges at the time of this inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	Clear Partly Turbid Very Turbid
Is a rain gauge installed on site?	Yes No
If yes, where is it located?	Nearby gauge, NOAA, COCORHAS and Weather Underground monitored for "Weather Events".
Has the Rain Event Page been filled out?	Vac No.



## **General Permit SWPPP Inspection** Horizon Village Site Name: Inspector: Greg Ciminera Horizon Village NMR10023D and NMR10023E C17E119 Permit #: Inspection Frequency: Bi-weekly Last Rain Event Last Precipitation 48h Forecast Apr 27, 2022, 7:58:18 AM Date of Visit: Saturday, April 2, 2022, 0.04" Thursday, March 24, 2022, 0.0" 1% Chance of Rain

Are there SDS	s Sr	neets	on	site?
---------------	------	-------	----	-------





If yes, where are they located?

Weather events are detailed at the end of each report.

If construction ceases on the site for	more than 14 days, the site must be stabilized until
construction resumes.	
Date Construction Stopped	
Date Constituenon Stopped	

**Date Construction Resumed** 

10/21

08/20

Measures Taken to Stabilize the Site:

Streets with curb and gutter are in place. Rip rap retention ponds are in place on the west end. Single retention pond, non rip rap in place in the southeast corner. Block walls in place southwest corner along west boundary, ending in the northwest corner. Hydro seeding on east side 10-20, silt fence added to the two west out falls 03-21.

## Construction Phasing

Completed:

nd were completed.

Verify what stage of construction the project is in, and record dates when active	<u>vities started ar</u>
Installed BMPs	Completed
Started:	07/20
Completed:	08/20
Site Clearing and Grading	Completed
Started:	07/20



### **General Permit SWPPP Inspection** Horizon Village Site Name: Inspector: Greg Ciminera Horizon Village NMR10023D and NMR10023E C17E119 Bi-weekly Inspection Frequency: Permit #: Last Rain Event Last Precipitation 48h Forecast Apr 27, 2022, 7:58:18 AM Date of Visit: Thursday, March 24, 2022, 0.0" Saturday, April 2, 2022, 0.04" 1% Chance of Rain

, , , , , , , , , , , , , , , , , , , ,	7.
Installing Utilities	Completed
Started:	09/20
Completed:	03/21
Building Structure	Started
Started:	10/21
Completed:	
Paving and Walks	
Started:	09/20
Completed:	02/21
Final Grading/Stabilize Site	Started
Started:	02/21
Completed:	03/21- Temp. Stabilization
Other	
Started:	

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log



si, v silvi	Consul Daweit CM/DDD Inspection						
	General P	ermit SWPPP Inspection	on				
Site Name:	<u>Horizon Village</u> <u>Horizon Village</u>	Inspector:	Greg Cimine	ra			
Permit #:	NMR10023D and NMR10023E C17E119	Inspection Frequency:	g: Bi-weekly				
Date of Visit:	Apr 27, 2022, 7:58:18 AM	Last Rain Event Thursday, March 24, 2022, 0.0"	Last Precipitation Saturday, April 2, 2022, 0.04"	48h Forecast 1% Chance of Rain			

LIST OT BIVIPS INSTAILED:	Rip Rap Retention Ponds, Chemical Toilet, Swales, Curb cut back, Paving in place with curb and gutter, Block Walls, dumpster.
Are all of the above controls installed?	Yes No
Do any of the above controls need maintenance?	Yes No
If any of the controls have not been installed or require maintenance, please list the control and explain.	Concrete waste outside of washout needs to be cleaned up.
Are the BMPs shown on the map?	Yes No
Were there any changes to the SWPPP?	Yes No
Has the SWPPP been updated?	Yes No
Were the changes to the SWPPP implemented within 7 days?	Yes No
List any new BMPs needed:	

# Oversight Issues

Notes:

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?









## **General Permit SWPPP Inspection** Horizon Village Site Name: Inspector: Greg Ciminera Horizon Village NMR10023D and NMR10023E C17E119 Bi-weekly Permit #: Inspection Frequency: Last Rain Event Last Precipitation 48h Forecast Date of Visit: Apr 27, 2022, 7:58:18 AM Thursday, March 24, 2022, 0.0" Saturday, April 2, 2022, 0.04" 1% Chance of Rain

## Maintenance Required? Yes N/A 3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained? Implemented? N/A Yes No Maintenance Required? N/A Yes No 4. Are discharge points and receiving waters free of any sediment deposits? Implemented? N/A No Yes Maintenance Required? Yes N/A 5. Are storm drain inlets properly protected? Implemented? N/A No Maintenance Required? N/A 6. Is the construction exit preventing sediment from being tracked into the street? Implemented? No N/A Maintenance Required? N/A Yes 7. Is trash/litter from work areas collected and placed in dumpsters? Implemented? Nο N/A Maintenance Required? N/A Yes 8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained? Implemented? N/A Yes Maintenance Required?

No

N/A



# General Permit SWPPP Inspection Site Name: Horizon Village Horizon Village Horizon Village Inspector: Greg Ciminera Permit #: NMR10023D and NMR10023E C17E119 Inspection Frequency: Bi-weekly Date of Visit: Apr 27, 2022, 7:58:18 AM Last Rain Event Thursday, March 24, 2022, 0.0" Last Precipitation Saturday, April 2, 2022, 0.04" 48h Forecast 19% Chance of Rain

Bute of Visite		Thursday, March 24, 2022, 0.0"	Saturday, Apı	ril 2, 2022, 0.04"	1% Chance of Rai
Implemented	?		Yes No	N/A	
Maintenance	Required	[	Yes No	N/A	
10. Are materia	als that are potential storm water con	taminants stored inside or u	under cover?		
Implemented <sup>*</sup>	?	[	Yes No	N/A	
Maintenance	Required?		Yes No	N/A	
11. Are non-sto	<u>rm water discharges (e.g., wash water</u>	<u>, dewatering) properly cont</u>	rolled?		
Implemented <sup>*</sup>	?		Yes No	N/A	
Maintenance	Required?		Yes No	N/A	
12. Has the Site	map been updated to reflect current	conditions?			
Implemented <sup>*</sup>	?		Yes No	N/A	
Maintenance	Required?	[	Yes No	N/A	
<u>13. Is the NOI p</u>	osted?				
Implemented	?		Yes No	N/A	
Maintenance	Required?		Yes No	N/A	
14. Were previo	ous corrections made within 7 days of	last inspection or before the	e next storm	event?	
Implemented <sup>®</sup>	?	[	Yes No	N/A	
Maintenance	Required?		Yes No	N/A	

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?







## **General Permit SWPPP Inspection** Horizon Village Site Name: Inspector: Greg Ciminera Horizon Village NMR10023D and NMR10023E C17E119 **Inspection Frequency:** Bi-weekly Permit #: Last Rain Event Last Precipitation 48h Forecast Date of Visit: Apr 27, 2022, 7:58:18 AM Thursday, March 24, 2022, 0.0" Saturday, April 2, 2022, 0.04" 1% Chance of Rain

Have there been	า any	reportable	quantities	releases	of haza	rdous
materials?						

Yes

No

Additional Notes

# Certification & Signatures

## Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature - Inspector	
X Greg Ciminera	Date Apr 29, 2022
Title Inspector	
Electronic Signature - Site Operator ${f X}$	Date
Title	



General Permit SWPPP Inspection						
Site Name: Horizon Village Inspector: Greg Ciminera						
Permit #:	NMR10023D and NMR10023E C17E119	Inspection Frequency:	Bi-weekly			
Date of Visit:	Apr 27, 2022, 7:58:18 AM	Last Rain Event Thursday, March 24, 2022, 0.0"	Last Precipitation Saturday, April 2, 2022, 0.04"	48h Forecast 1% Chance of Rain		

# **Weather History**

Precipitation Recorded					No Precipitation					Missed or data unavailable			
April													
<b>14</b> th	0	<b>15</b> th	0	<b>16</b> th	0	<b>17</b> th	0 <b>18</b> th	0	<b>19</b> th	0	<b>20</b> th	0	
<b>21</b> st	0	<b>22</b> nd	0	<b>23</b> rd	0	<b>24</b> th	0 <b>25</b> th	0	<b>26</b> th	0	<b>27</b> th	0	

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



General Permit SWPPP Inspection								
Site Name:	<u>Horizon Village</u> <u>Horizon Village</u>	Inspector:	Inspector: Greg Ciminera					
Permit #:	NMR10023D and NMR10023E C17E119	Inspection Frequency:	Bi-weekly					
Date of Visit:	Apr 27, 2022, 7:58:18 AM	Last Rain Event Thursday, March 24, 2022, 0.0"	Last Precipitation Saturday, April 2, 2022, 0.04"	48h Forecast 1% Chance of Rain				

# Action Items

Title	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Imgs
Ci LATE  Concrete waste	Greg Ciminera	April 14, 2022	7 Days	Aloft and aerostat	Concrete was outside of washout	Open			
Ci LATE  Concrete waste	Greg Ciminera	March 30, 2022	7 Days	Aerostat aloft	Concrete waste out of proper container.	Open			Photo 1 Photo 2
Ci LATE  Concrete waste	Greg Ciminera	March 16, 2022	7 Days	Aerostat and aloft	Concrete waste needs to be cleaned up and put in proper washout container	Open			Photo 1 Photo 2 Photo 3 Photo 4
Ci LATE	Greg Ciminera	March 2, 2022	7 Days	Aerostat and aloft	Concrete waste outside of proper container	Open			Photo 1  Photo 2  Photo 3  Photo 4  Photo 5
Ci LATE  Concrete waste	Greg Ciminera	February 16, 2022	7 Days	Aerostat and aloft	Concrete waste on ground needs to be cleaned up washouts used	Open			Photo 1  Photo 2  Photo 3  Photo 4  Photo 5  Photo 6  Photo 7
CILATE  concrete waste	Greg Ciminera	January 20, 2022	7 Days	aerostat and aloft	concrete waste at aerostat and aloft. Needs to be put in proper container.	Open			Photo 2
Ci LATE  washouts	Greg Ciminera	December 23, 2021	7 Days	Aloft PI NE, Aerostat PI NE	Concrete waste on site needs to be cleaned up and put in a washout	Open		January 6, 2022Concrete waste still outside of washout at aloft PI NE and Aerostat PL NE	Photo 1 Photo 2
Concrete waste	Greg Ciminera	April 27, 2022	7 Days	Aloft aerostat	Concrete waste outside of washout	Open			Photo 1 Photo 2 Photo 3 Photo 4