

General Permit SWPPP Inspection Paseo Nuevo Parking Lot Site Name: Inspector: Jeff Hart 99999 Holly Ave NE, Albuquerque, NM 87113 Permit #: NMR1002WY, NMR1002WZ C18E074A Bi-weekly -**Inspection Frequency:** Last Rain Event Last Precipitation 48h Forecast **Date of Visit:** Jun 1, 2021, 4:36:15 PM Friday, June 4, 2021, 0.02" Sunday, June 6, 2021, 0.07" 19% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not compliance, press the "Add Action Item" button above to add a corrective action.	t applicable). If any of the items below are out of
General Information	
<u>Inspector's Qualifications</u> Trained and work experience - see inspector qualification page in section 2 of the SV	WPPP.
Type of Inspection:	Regular During storm event
	Post-storm event
Weather Information	
<u>Last Storm Event Information</u> For information on the last storm event, see the weather event information at the e	end of this inspection.
Weather at time of this inspection?	Clear Cloudy Rain
	Sleet Snowing High Winds
	Partly Cloudy
Have any discharges occurred since the last inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	
Are there any discharges at the time of this inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	
Is a rain gauge installed on site?	Yes No
If yes, where is it located?	Removed for final. Nearby gauge, NOAA, COCORHAS and Weather Underground monitored as secondary resources.
Has the Rain Event Page been filled out?	Yes No



General Permit SWPPP Inspection Paseo Nuevo Parking Lot Site Name: Inspector: Jeff Hart 99999 Holly Ave NE, Albuquerque, NM 87113 Permit #: NMR1002WY, NMR1002WZ C18E074A **Inspection Frequency:** Bi-weekly -Last Precipitation Last Rain Event 48h Forecast Date of Visit: Jun 1, 2021, 4:36:15 PM Sunday, June 6, 2021, 0.07" Friday, June 4, 2021, 0.02" 19% Chance of Rain

Are	there	SDS	sheets	on	site?
-----	-------	-----	--------	----	-------

Started:





16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
If yes, where are they located?	Inspectors log updated. Weather events detailed at the end of each report. Removed for final.
If construction ceases on the site for more than 14 days, the site construction resumes.	e must be stabilized until
Date Construction Stopped	12/20
Date Construction Resumed	
Measures Taken to Stabilize the Site:	Between phases.
Construction Phasing	
Verify what stage of construction the project is in, and record dates when activi	ties started and were completed.
Installed BMPs	Completed
Started:	07/20
Completed:	07/20
Site Clearing and Grading	Completed
Started:	07/20
Completed:	08/20
Installing Utilities	



General Permit SWPPP Inspection Paseo Nuevo Parking Lot Site Name: Inspector: Jeff Hart 99999 Holly Ave NE, Albuquerque, NM 87113 Permit #: NMR1002WY, NMR1002WZ C18E074A **Inspection Frequency:** Bi-weekly -Last Precipitation Last Rain Event 48h Forecast Jun 1, 2021, 4:36:15 PM **Date of Visit:** Sunday, June 6, 2021, 0.07" Friday, June 4, 2021, 0.02" 19% Chance of Rain

Completed:	
Building Structure	
Started:	
Completed:	
Paving and Walks	Completed
Started:	07/20
Completed:	10/20
Final Grading/Stabilize Site	Started
Started:	10/20
Completed:	
Other	
Started:	
Site-specific BMPs	
The corrective actions initiated and date completed are in the Corrective Action Log	
List of BMPs Installed:	Silt fence, Paved access pad, Retaining wall, Drop inlet protection, Curbs, Rip- Rap Swale, Pond, Wattles, Paving in place.
Are all of the above controls installed?	Yes No
Do any of the above controls need maintenance?	Yes No



General Permit SWPPP Inspection				
Site Name:	<u>Paseo Nuevo Parking Lot</u> <u>99999 Holly Ave NE, Albuquerque, NM 87113</u>	Inspector: Jeff Hart		t
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	: Bi-weekly -	
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain

	, -
If any of the controls have not been installed or require maintenance, please list the control and explain.	Minor silt fence repairs required along Holly and at rip rap pond. Slope stabilization NW side at garage.
Are the BMPs shown on the map?	Yes No
Were there any changes to the SWPPP?	Yes No
Has the SWPPP been updated?	Yes No
Were the changes to the SWPPP implemented within 7 days?	Yes No
List any new BMPs needed:	NO changes to the SWPPP
Notes:	Between phases.
Oversight Issues	

Implemented?

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented? No N/A Maintenance Required? No N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

No N/A Maintenance Required? Yes N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented? N/A



General Permit SWPPP Inspection				
Site Name: Paseo Nuevo Parking Lot 99999 Holly Ave NE, Albuquerque, NM 87113 Inspector: Jeff Hart				t
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	: Bi-weekly -	
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain

Date of VISIT:	Jun 1, 2021, 4:36:15 PM	Friday, June 4, 2021, 0.02"	Sunday, June 6, 2021, 0.07"	19% Chance
Maintenance Red	quired?	Y	/es No N/A	
4. Are discharge po	pints and receiving waters free of any s	sediment deposits?		
Implemented?		Y	/es No N/A	
Maintenance Red	quired?	Y	/es No N/A	
5. Are storm drain	inlets properly protected?			
Implemented?		Y	/es No N/A	
Maintenance Rec	quired?	Y	res No N/A	
6. Is the construct	ion exit preventing sediment from beir	ng tracked into the street	?	
Implemented?		Y	/es No N/A	
Maintenance Red	quired?	У	/es No N/A	
7. Is trash/litter from	om work areas collected and placed in	dumpsters?		
Implemented?		Y	/es No N/A	
Maintenance Red	quired?	У	res No N/A	
8. Are washout fac	<u>illities (e.g., paint, stucco, concrete) ava</u>	<u>ailable, clearly marked, ai</u>	nd maintained?	
Implemented?		Y	/es No N/A	
Maintenance Red	quired?	Y	/es No N/A	

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?



General Permit SWPPP Inspection				
Site Name:	<u>Paseo Nuevo Parking Lot</u> <u>99999 Holly Ave NE, Albuquerque, NM 87113</u>	Inspector: I left Hart		
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	Bi-weekly -	
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain

	Triday, june 4, 2021, 0.02 Sunday, june 0, 2021, 0.0
Maintenance Required	Yes No N/A
10. Are materials that are potential storm water contami	inants stored inside or under cover?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
11. Are non-storm water discharges (e.g., wash water, de	watering) properly controlled?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
12. Has the Site map been updated to reflect current con	ditions?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
13. Is the NOI posted?	
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
14. Were previous corrections made within 7 days of last	inspection or before the next storm event?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?







General Permit SWPPP Inspection				
Site Name:	<u>Paseo Nuevo Parking Lot</u> 99999 Holly Ave NE, Albuquerque, NM 87113	Inspector:	Inspector: Jeff Hart	
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	Bi-weekly -	
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain

Have there been any reportable quantities releases of hazardous materials?





Additional Notes

Berm along the NW, to the first level parking garage, requires stabilization. Minor silt repairs required. No active work. Site is between phases. Weather event 05/31/21= 1.25".

Certification & Signatures

Certification Statement:

 $\hat{a} \in \mathbb{C}$ certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. $\hat{a} \in \mathbb{D}$

Electronic Signature

X Jeff Hart Date June 7, 2021 at 9:32:30 AM MDT

Title Senior Inspector



General Permit SWPPP Inspection				
Site Name: Paseo Nuevo Parking Lot 99999 Holly Ave NE, Albuquerque, NM 87113 Inspector: Jeff Hart				t
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	Bi-weekly -	
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain

Weather History

	Precipitat Recorded			o recipitation		Missed or data unavailable	a
May							
18 th0.32"	19 th	0 20 th	0 21 st	0 22 nd	0 23 rd	0 24 th	0
25 th 0	26 th	0 27 th	0 28 th	0 29 th	0 30 th 0).01" 31 st 1	1.25"
June							
1 st	0 3	rd	4 th	⊘ 5 tl		6 th	\bigcirc

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



General Permit SWPPP Inspection									
Site Name:	<u>Paseo Nuevo Parking Lot</u> <u>99999 Holly Ave NE, Albuquerque, NM 87113</u>	Inspector:	Jeff Hart						
Permit #:	NMR1002WY, NMR1002WZ C18E074A	Inspection Frequency:	Bi-weekly -						
Date of Visit:	Jun 1, 2021, 4:36:15 PM	Last Rain Event Friday, June 4, 2021, 0.02"	Last Precipitation Sunday, June 6, 2021, 0.07"	48h Forecast 19% Chance of Rain					

There Are No Action Items