

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C18E075		Project Name:	Stillbrook @ Sevano Place Subdivision				
NPDES Id. No.	NMR10039X & NMR1003UE		Location:	6300 Alameda Blvd. NE				
1/25/2024		Owner			Contractor			
Operator		Clearbrook Investments, Inc			Stillbrooke Homes			
Contact name & title		Chris Kelsey			Chris Kelsey			
e-mail		ckelsey@stillbrooke.com			ckelsey@stillbrooke.com			
Contact Phone #		505-858-1800			505-858-1800			
COA Insp	COA Inspector		Doug Hughes			rt/End Time: 4pm		
	Construction Phase:					house		
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of i		inspection? Rain			Temperature: ~ 45			
Estimated date of last storm 0.25" or greater 1/4/2024								
ltem Number	Deficiency/ Corrective Action							
1	none							
2	In accordance with City Ordinance § 14-5-2-11(C)(1), self-inspections must continue until the site is "determined as stabilized by the city." The property owner/operator is responsible for determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfied and then for filing their Notice of Termination (NOT) with the EPA. Each operator may terminate CGP coverage only if one or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 has occurred. After filing the NOT with the EPA, the property owner is responsible for requesting a Determination of Stabilization from the City.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	?	Latest re	port Date:	?		

Notes:					
Last house	e nearly complete. Please file NOT and request stabilization determination after construction is				
complete.					

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes 924-3420 jhughes@CABQ.gov

1/29/24

James D. Hughes