

## City of Albuquerque Stormwater Construction Site Inspection Report

			General li	ntormation				
ESC File No.	C18E	075	Project Name:		Stillbrook @ Sevano Place Subdivision			
NPDES Id. No.	NMR10039X & NMR1003UE L		Location:		6300 Alameda Blvd. NE			
1/25/2024		Owner		Contractor				
Operator		Clearbrook Investments, Inc			Stillbrooke Homes			
Contact name & title		Chris Kelsey			Chris Kelsey			
e-mail		ckelsey@stillbrooke.com			ckelsey@stillbrooke.com			
Contact Phone #		505-858-1800			505-858-1800			
COA Inspector		Doug Hughes			Start/End Time	ne: 4pm		
Construction Phase:					house			
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	inspection?	Rair	1	Tempe	rature: ~	45	
Estimated	date of last s	storm 0.25"	or greater		1/4/2024			
Item Number	Deficiency/ Corrective Action							
1	none							
2	In accordance with City Ordinance § 14-5-2-11(C)(1), self-inspections must continue until the site is "determined as stabilized by the city." The property owner/operator is responsible for determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfied and then for filing their Notice of Termination (NOT) with the EPA. Each operator may terminate CGP coverage only if one or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 has occurred. After filing the NOT with the EPA, the property owner is responsible for requesting a Determination of Stabilization from the City.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	?	Latest re	port Date:	?		
					•			

Notes:				
Last house nearly complete. Please file NOT and request stabilization determination after construction is				
complete.				

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes 924-3420

jhughes@CABQ.gov