

### **INSPECTION REPORT**

### **GENERAL INFORMATION**

| DATE OF INSPECTION:         | 9/29/2020  |
|-----------------------------|--|
| COMPANY NAME:               | Sevano Development, LLC  |
| PROJECT NAME:               | Sevano Place Subdivision   |
| LOCATION:                   | Sevano Loop,Albuquerque,New Mexico,87113   |
| TRACKING NO:                | NMR10039R, NMR10039X, NMR1003B0  |
| COMPLIANCE EVALUATION:      | Satisfactory   |
| TYPE OF INSPECTION:         | 14Day  |
| START TIME:                 | 11:53 AM   |
| END TIME:                   | 12:05 PM   |
| INSPECTOR'S NAME:           | Ray Welton   |
| INSPECTOR'S TITLE:          | NPDES Inspector  |
| INSPECTOR'S QUALIFICATIONS: | StormwaterONE  |
| INSPECTOR'S CONTACT:        | 505-400-7500   |
| PHASE OF CONSTRUCTION:      | <ul> <li>✓ Clear and Grub</li> <li>✓ Excavation</li> <li>☐ Building (vertical)</li> <li>☐ Rough Grading</li> <li>☐ Final Grading</li> <li>☐ Final Stabilization</li> </ul> |
|                             |  |

## **WEATHER INFORMATION**

| HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?   | Yes   | <ul><li>No</li></ul> |
|---|-------|----------------------|
| WEATHER AT TIME OF THIS INSPECTION:                     | Clear |                      |
| TEMPERATURE:  | 67    |                      |
| HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? | Yes   | <ul><li>No</li></ul> |
| ARE ANY DISCHARGES OCCURRING NOW?                       | Yes   | <ul><li>No</li></ul> |
| ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?        | Yes   | <ul><li>No</li></ul> |

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

| # | S&E/P2<br>CONTROLS           | MAINTENANCE | CORRECTIVE<br>ACTION | LOCATION        | QUANTITY | UNIT | рното |
|---|------------------------------|-------------|----------------------|-----------------|----------|------|-------|
| 1 | NPDES Permit<br>Notification | None        | None                 | Signal Ave      | 1        | EA   | Yes   |
| 2 | Construction<br>Entrance     | None        | None                 | Signal Ave      | 1        | EA   | Yes   |
| 3 | Silt Fence                   | None        | None                 | South Perimeter | 250      | LF   | Yes   |
| 4 | Silt Fence                   | None        | None                 | West Perimeter  | 250      | LF   | Yes   |
| 5 | Silt Fence                   | None        | None                 | North Perimeter | 250      | LF   | Yes   |
| 6 | Silt Fence                   | None        | None                 | East Perimeter  | 250      | LF   | Yes   |

### **GENERAL SITE INSPECTION ITEMS**

| # | INSPECTION ITEM   | INSPECTOR'S<br>OBSERVATION | ACTION REQUIRED? | NOTES   |
|---|---|----------------------------|------------------|---|
| 1 | Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?   | • Yes ONo ON/A             | Yes No           | SWPPP signage clearly<br>posted with the correct<br>information and properly<br>displayed at an obvious<br>perimeter location |
| 2 | Are steep slope areas not actively being worked properly stabilized?  | Yes No N/A                 | Yes No           | Silt Fence stabilized and protected areas.  |
| 3 | Are disturbed areas not actively being worked properly stabilized?  | • Yes ONo ON/A             | Yes No           | Silt Fence stabilized and protected areas.  |
| 4 | Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?            | Yes No N/A                 | Yes No           | Silt Fence stabilized and protected areas.  |
| 5 | Are discharge points and receiving waters free of any sediment deposits?  | Yes No N/A                 | Yes No           |   |
| 6 | Is trash/litter from work areas collected and placed in covered dumpsters?  | Yes No N/A                 | Yes No           |   |
| 7 | Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?                             | Yes No N/A                 | Yes No           | Washout not viewed onsite   |
| 8 | Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material? | • Yes ONo ON/A             | ○Yes             |   |
| 9 | Are materials that are potential stormwater contaminants stored inside or in containers?                                    | Yes No N/A                 | Yes No           |   |

| #  | INSPECTION ITEM   | INSPECTOR'S<br>OBSERVATION | ACTION REQUIRED? | NOTES   |
|----|---|----------------------------|------------------|---|
| 10 | Are offsite flows entering the construction site?   | ○Yes ● No ○ N/A            | Yes No           | No offsite flows entering the construction site   |
| 11 | Is there any evidence that pollutants are leaving the site or are not properly contained on site?   | ○ Yes ● No ○ N/A           | Yes No           | No evidence that pollutants are leaving the site  |
| 12 | Are traffic and parking areas restricted so as to reduce soil erosion and dust?   | • Yes ONO N/A              | Yes No           |   |
| 13 | Are non-stormwater discharges properly controlled?  | • Yes ONo ON/A             | Yes No           |   |
| 14 | Is the project being operated in compliance with the SWPPP and with permit conditions at this time?   | ● Yes ○ No ○ N/A           | ◯ Yes ● No       | Project being operated in compliance with the SWPPP and with permit conditions at this time |
| 15 | Are changes to the SWPPP necessary at this time?  | Yes ● No N/A               | Yes No           | No are changes to the SWPPP necessary at this time  |
| 16 | Are dust control measures being properly implemented?   | ● Yes ○ No ○ N/A           | Yes No           | Water truck onsite to<br>ensure dust control<br>measures are being<br>properly implemented  |
| 17 | Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates) | • Yes O No O N/A           | ○Yes • No        | Book not viewed onsite.<br>SWPPP contact<br>information provided.                           |

## **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

| INSPECTED BT. Tray Wellott DATE. October 01, 20 | INSPECTED BY: | Ray Welton | <b>DATE:</b> October 01, 2020 |
|---|---------------|------------|-------------------------------|
|---|---------------|------------|-------------------------------|

SIGNATURE AND AFFILIATION:

#### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

| PRINT NAME AND TITLE: | , | DA | ATE: |
|-----------------------|---|----|------|
|                       |   |    |      |

SIGNATURE: