

### **INSPECTION REPORT**

## **GENERAL INFORMATION**

DATE OF INSPECTION:	3/16/2021
COMPANY NAME:	Sevano Development, LLC
PROJECT NAME:	Sevano Place Subdivision
LOCATION:	Sevano Loop, Albuquerque, New Mexico, 87113
TRACKING NO:	NMR10039R, NMR10039X, NMR1003B0
COMPLIANCE EVALUATION:	Marginal
TYPE OF INSPECTION:	14Day
START TIME:	12:38 PM
END TIME:	12:53 PM
INSPECTOR'S NAME:	Ray Welton
INSPECTOR'S TITLE:	NPDES Inspector
INSPECTOR'S QUALIFICATIONS:	StormwaterONE
INSPECTOR'S CONTACT:	505-400-7500
PHASE OF CONSTRUCTION:	<ul> <li>✓ Clear and Grub ✓ Excavation ☐ Building (vertical)</li> <li>☐ Rough Grading ✓ Infrastructure ☐ Final Grading</li> <li>☐ Final Stabilization</li> </ul>

# **WEATHER INFORMATION**

LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	59	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	None	None	Signal Ave	1	EA	Yes
2	NPDES Permit Notification	None	None	Signal Ave	1	EA	Yes
3	Silt Fence	None	None	South Perimeter	100	LF	Yes
4	Construction Entrance	None	None	Signal Ave Entrance	1	EA	Yes
5	Silt Fence	None	None	South Perimeter	100	LF	Yes
6	Concrete Washout	Clean	None	Onsite	1	EA	Yes
7	Debris or Waste	Remove	None	Onsite	1	EA	Yes

## **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes ONo ON/A	Yes No	SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location.
2	Are steep slope areas not actively being worked properly stabilized?	Yes No N/A	Yes No	Silt fence, block wall and curb protected and stabilized areas.
3	Are disturbed areas not actively being worked properly stabilized?	Yes No N/A	Yes No	Silt fence, block wall and curb protected and stabilized areas.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	● Yes ○ No ○ N/A	Yes No	Silt fence, block wall and curb protected and stabilized areas.
5	Are discharge points and receiving waters free of any sediment deposits?	Yes No N/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	Yes No	Dried concrete debris requires removal.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	Yes ● No N/A	Yes No	Concrete washout requires cleaning.
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	• Yes ONo ON/A	○Yes	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes No N/A	Yes No	
10	Are offsite flows entering the construction site?	Yes ● No N/A	Yes No	No offsite flows entering the construction site.
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes ● No N/A	Yes No	No evidence that pollutants are leaving the site.
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	● Yes ○ No ○ N/A	Yes No	Dried concrete debris requires removal. Concrete washout requires cleaning.
15	Are changes to the SWPPP necessary at this time?	Yes ● No N/A	Yes No	No changes to the SWPPP necessary at this time.
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	• Yes ONo ON/A	○Yes	Book not viewed onsite.

#### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Ray Welton	DATE: March 17	7. 2021

SIGNATURE AND AFFILIATION:

### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	DATE
-----------------------	------

