

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	. C18E085		roject Name:		Allaso Olivine			
NPDES Id. No.	NPDES Id. No. NMR10059X & '5C		ocation: 6925 Alameda Blvd NE			ieda Blvd NE		
1/25/2024					Contractor			
Operator		Titan Olivine, LLC			НВ			
Contact name & title		Josh Rogers			Zach Gruen VP & Matthew Barnard SI			
e-mail		jrogers@titan-development.com			zachg@Hbconstruction.com & leer@'			
Contact Phone #		505-998-0111			856-0404 & 250-2069			
COA Inspector		Doug Hughes			Start/End Time:	4pi	n	
Construction Phase:		framing/vertical						
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	spection? rain			Temperature: ~ 45		
Estimated date of last storm 0.25" or greater 1/4/2024								
Item	Deficiency/Corrective Action							
Number	Deficiency/ Corrective Action							
1	None							
2								
3								
2.1	Discharge off site?	(Y/N)	yes					
4	Self Inspection Reports			Latest re	est report Date: 1/8/2024		24	

Notes:	
The SWPP	PP was located in the construction Trailer.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

1/29/2024

James D. Hughes