

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	C18E085		Project Name:	Allaso Olivine			
NPDES Id. No.	NMR10059X & '5CC		Location:		Louisiana at Oakland		
1,20,2020		Owner	-		Contractor		
Operator		Pulte Homes			HB		
Contact name & title		Titan Olivine, LLC			Zach Gruen & Lee Riley		
e-mail		jrogers@titan-development.com			zachg@Hbconstruction.com & leer@'		
Contact Phone #		505-998-0111			856-0404 & 250-2069		
COA Inspector		Doug Hughes			Start/End Time: 10:35 AM		
Construction Phase:					/grading/vertica		
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up
Weather at time of i		nspection? clear		Temperature: ~ 50			
Estimated date of last storm 0.25			or greater		3/16/2023		
Item							
	Deficiency/ Corrective Action						
Number							
1	None						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports		Latest re	port Date:	4/17/2	023

Notes: The SWPPP was missing from the sight

Posting was up and no sediment in the street. The BMPs (SF) was in good shape.

FYI - After all areas have been stabilized, you must verify that the "Final Stabilization Criteria" of CGP 2.2.14.c has been satisfied. This step is independent of the Certificate of Occupancy (CO) process. Then satisfy the other "Conditions for Terminating CGP Coverage" per CGP 8.2 including removal of BMPs. Next, file your "Notice of Termination" (NOT) with the EPA. Please copy me with the documentation and the EPA's acceptance of the NOT.

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505) 924-3420 jhughes@cabq.gov