



General Permit SWPPP Inspection

Site Name:	<u>Allaso Olivine</u> <u>Allaso Olivine</u>	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly	
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4"	48h Forecast 67% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ Regular☐ During storm event
- ☒ Post-storm event

Weather Information

Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☐ Clear☐ Cloudy☐ Rain☐ Sleet☐ Snowing
- ☐ High Winds☒ Partly Cloudy

Have any discharges occurred since the last inspection?

- Yes
- No

If yes, what did the water look like at the time of the discharge?

- Clear
- Partly Turbid
- Very Turbid

Are there any discharges at the time of this inspection?

- Yes
- No

If yes, what did the water look like at the time of the discharge?

- Clear
- Partly Turbid
- Very Turbid

Is a rain gauge installed on site?

- Yes
- No

If yes, where is it located?

Representative weather site is used to measure precipitation.

Has the Rain Event Page been filled out?

- Yes
- No

Are there SDS sheets on site?

- Yes
- No

If yes, where are they located?

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Completed

Started:

Completed:

3/2023

Site Clearing and Grading

Started

Started:

3/2023

Completed:

General Permit SWPPP Inspection

Site Name:	<u>Allaso Olivine</u> <u>Allaso Olivine</u>	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly	
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4"	48h Forecast 67% Chance of Rain

Installing Utilities	<input type="text"/>
Started:	<input type="text"/>
Completed:	<input type="text"/>
Building Structure	<input type="text"/>
Started:	<input type="text"/>
Completed:	<input type="text"/>
Paving and Walks	<input type="text"/>
Started:	<input type="text"/>
Completed:	<input type="text"/>
Final Grading/Stabilize Site	<input type="text"/>
Started:	<input type="text"/>
Completed:	<input type="text"/>
Other	<input type="text"/>
Started:	<input type="text"/>

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Silt fence, stabilized construction entrance, portable toilet

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No

If any of the controls have not been installed or require maintenance, please list the control and explain.

Are the BMPs shown on the map?

Yes

No

Were there any changes to the SWPPP?

Yes

No

Has the SWPPP been updated?

Yes

No

Were the changes to the SWPPP implemented within 7 days?

Yes

No

List any new BMPs needed:

No new BMP's needed at this time.


Notes:

Dirt work in progress.

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

<div><div></div><div>INSPECTIONS PLUS</div></div>				
General Permit SWPPP Inspection				
Site Name:	<u>Allaso Olivine</u> <u>Allaso Olivine</u>	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly	
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4"	48h Forecast 67% Chance of Rain

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

5. Are storm drain inlets properly protected?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Yes

No

N/A

Maintenance Required

Yes

No

N/A

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

12. Has the Site map been updated to reflect current conditions?



General Permit SWPPP Inspection

Site Name:	<u>Allaso Olivine</u> <u>Allaso Olivine</u>	Inspector:	Marcos Valadez		
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly		
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4"	48h Forecast 67% Chance of Rain	

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

13. Is the NOI posted?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

Yes

No

N/A

Maintenance Required?

Yes

No

N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes

No

Have there been any reportable quantities releases of hazardous materials?

Yes

No

Additional Notes

The site looked good at the time of inspection. This is the first swppp inspection.

Certification & Signatures

Certification Statement:
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature - Inspector

X

Marcos Valadez

Date
Mar 20, 2023

Title
Inspector

Electronic Signature - Site Operator

X

Date

Title

General Permit SWPPP Inspection

Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly	
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4"	48h Forecast 67% Chance of Rain

Photos




General Permit SWPPP Inspection

Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4" 48h Forecast 67% Chance of Rain

Weather History




December



January




February



March



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



INSPECTIONS
PLUS

General Permit SWPPP Inspection			
Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez
Permit #:	NMR10059X	Inspection Frequency:	Bi-weekly
Date of Visit:	Mar 20, 2023, 8:16:10 AM	Last Rain Event --	Last Precipitation Friday, March 17, 2023, 0.4" 48h Forecast 67% Chance of Rain

There Are No Action Items