

Weather Event Inspection

Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:		
Date of Visit:	Mar 21, 2023, 12:34:18 PM	Last Rain Event --	Last Precipitation Monday, March 20, 2023, 0.56"	48h Forecast 69% Chance of Rain

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

a. Site Inspection

1. Are there any erosion control structures damaged from the rain event?

Yes

No

Notes:

2. Are there signs of new ruts or gullies from the rain event?

Yes

No

Notes:

3. Are there signs of significant amounts of mud in the street or outfalls from the rainfall event?

Yes

No

Notes:

4. Are there any conditions that need immediate attention?

Yes

No

Notes:

All BMP's in place.

Part 2: Inspection report summary.

b. Inspection Report Summary

1. Qualifications of Inspector:

Training and work experience – see inspector qualification page in the SWPPP.

2. Measures/Areas Inspected:

Entire site.

3. Observed Conditions:

Good.

4. Changes Necessary to the SWPPP:

No

5. Were there any discharges?

Yes

No

Notes:

No discharges observed during the inspection.

6. What did the water look like at the time of the discharge?

☐ Clear

☐ During storm event

☐ Very sandy

Notes:

N/A

7. Was Inspection Conducted Within 24 Hours of Last Rainfall Over 1/4"?

Yes

No

Notes:

8. How much did it rain?

Reference precipitation values included with this form.

Notes:

0.53 inches of precipitation.



INSPECTIONS PLUS

Weather Event Inspection

Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez	
Permit #:	NMR10059X	Inspection Frequency:		
Date of Visit:	Mar 21, 2023, 12:34:18 PM	Last Rain Event --	Last Precipitation Monday, March 20, 2023, 0.56"	48h Forecast 69% Chance of Rain

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature - Inspector

X *Marcos Valadez*

Date
Mar 21, 2023

Title
Inspector

Electronic Signature - Site Operator

X

Date _____


Title

Weather Event Inspection

Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez
Permit #:	NMR10059X	Inspection Frequency:	
Date of Visit:	Mar 21, 2023, 12:34:18 PM	Last Rain Event --	Last Precipitation Monday, March 20, 2023, 0.56" 48h Forecast 69% Chance of Rain

Photos



<div><div></div><div>INSPECTIONS PLUS</div></div>			
Weather Event Inspection			
Site Name:	Allaso Olivine Allaso Olivine	Inspector:	Marcos Valadez
Permit #:	NMR10059X	Inspection Frequency:	
Date of Visit:	Mar 21, 2023, 12:34:18 PM	Last Rain Event --	Last Precipitation Monday, March 20, 2023, 0.56" 48h Forecast 69% Chance of Rain

There Are No Action Items