City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Mixed Use		
Location:	Alameda and Signal		
Site Contact Name & Agency	Tom Martinez - Snyder Construction	ESC File No.	C18E086
	tmartinez@snyder-const.com	NPDES Id. No.	NMR1001TQ
Inspection Date:	06/13/19	Start/End Time:	0800/0830hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	foundations		

Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"		311/Complaint	x	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	69*
Estimated date of last storm 0.25" or greater		5/11/2019	

Item Number	Deficiency/ Corrective Action			
1	no new issues observed, silt fence and construction entrance requires maintenance			
	A follow up inspection will occur Monday 06/17/19.			
2	Please provide latest SWPPP self-inspection report			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	5/24/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.06.13 10:15:06 -06'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 06/13/19