

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Alameda Mixed Use					
Location:		Alameda and Signal					
Site Contact Name &		Tom Martinez - Snyder Construction ESC File No.			C18E086		
Agency		tmartinez@snyder-const.com NPDES Id. No.			NMR1001TQ		
Inspection Date:			art/End Time: 11	30/1145hrs			
CoA Stormwater Inspector: Timothy E. Sims							
	tion Phase:	foundations					
Type of Ir	spection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint x	Follow Up
347 11			01				07*
weath	er at time of	nspection? Clear torm 0.25" or greater			Temperature: ~ 87*		
Estimated	date of last	storm 0.25 or	greater			7/7/2019	
Item	Deficiency/Corrective Action						
Number	Deficiency/ Corrective Action						
1	Please provide latest SWPPP self-inspection report						
2	Domestic waste (water bottles) not in acceptable waste container. Please dispose and secure waste						
	in acceptable containers that are provided.						
3			•	site requires	maintenance.	. Please mitigate.	
4	Blow trash or	the east side of	f the site also rec	uires mitigat	ion.	-	
2.4		(1.16.1)		<u> </u>			
2.1	Discharge off site?	(Y/N)	No	1.1		0/0/200	10
4	Self Insped	ction Reports		Latest rep	ort Date:	8/9/201	19
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

08/13/19