



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Mixed Use		
Location:	Alameda and Signal		
Site Contact Name & Agency	Tom Martinez - Snyder Construction tmartinez@snyder-const.com	ESC File No.	C18E086
		NPDES Id. No.	NMR1001TQ
Inspection Date:	01/03/20	Start/End Time:	0830/0900hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	sitework and vertical construction		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	28*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 12/20/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/03/20