



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Mixed Use					
Location:	Alameda and Signal					
Site Contact Name & Agency	Tom Martinez - Snyder Construction	ESC File No.	C18E086			
	tmartinez@snyder-const.com	NPDES Id. No.	NMR1001TQ			
Inspection Date:	03/24/20	Start/End Time:	1030/1050hrs			
CoA Stormwater Inspector:	Timothy E. Sims					
Construction Phase:	sitework and vertical construction					
Type of Inspection:	<input checked="checked" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	52*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action			
	no new issues observed with this inspection			
	***Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	2/11/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 03/24/20