



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Mixed Use				
Location:	Alameda and Signal				
Site Contact Name & Agency	Tom Martinez - Snyder Construction	ESC File No.	C18E086		
	tmartinez@snyder-const.com	NPDES Id. No.	NMR1001TQ		
Inspection Date:	08/05/20	Start/End Time:	1000/1030hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	sitework and vertical construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	86*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 7/31/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/05/20