



City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Alameda Mixed Use					
Location:		Alameda and Signal					
Site Contact Name & Agency:		Gary Christensen - Snyder Construction	ESC File No.	C18E086			
		gchristensen@snyder-const.com	NPDES Id. No.	NMR1001TQ			
Inspection Date:		08/31/20	Start/End Time:	0910/0930hrs			
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		sitework and vertical construction					
Type of Inspection:		<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" x	<input checked="" type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up	

Weather at time of inspection?		Clear	Temperature: ~	86*
Estimated date of last storm 0.25" or greater			8/29/2020	

Item Number	Deficiency/ Corrective Action			
1	Silt fence is required on the NW pad site and ponding area. If construction has stopped for 14 days stabilization should occur per the General Permit			
2	Silt fence is required on the east pad site on the north and west sides. If construction has stopped for 14 days stabilization should occur per the General Permit.			
3	Inspection reports are required until final stabilization has occurred.-(Thanks for the reports)			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	8/31/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/31/20 _____