



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C18E086	Project Name:	Alameda Mixed-Use		
NPDES Id. No.	NMR1001U5	Location:	6100 Alameda NE		
6/1/2021	Owner	Contractor			
Operator	Green Jeans West, LLC.		Snyder Construction		
Contact name & title	Roy Solomon		Gary Christensen		
e-mail	roy@roysolomon.org		gchristensen@snyder-const.com		
Contact Phone #	505-401-1000		505-720-8475		
COA Inspector	Thomas Evans		Start/End Time:	2:40 PM-2:45 PM	
Construction Phase:	Stabilization/inactive				
Type of Inspection:		Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	clear		Temperature:	~ 84	
Estimated date of last storm 0.25" or greater	5/31/2021				
Item Number	Deficiency/ Corrective Action				
1	Silt fence not properly installed. Repair/replace downed silt fence on both East and West ends of the property.				
2	Sediment on the sidewalk. Remove sediment from the sidewalk/street daily.				
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	5/19/2021	

Notes:	Post-rain event on May 31, 2021.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 06/07/2021