



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C18E086	Project Name:	Alameda Mixed-Use		
NPDES Id. No.	NMR1001U5	Location:	6100 Alameda NE		
11/15/2021	Owner	Contractor			
Operator	Green Jeans West, LLC.	Snyder Construction			
Contact name & title	Roy Solomon	Terminated			
e-mail	roy@roysolomon.org				
Contact Phone #	505-401-1000				
COA Inspector	James Hughes	Start/End Time:	11:30am		
Construction Phase:	Stabilization/inactive				
Type of Inspection:		Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?		clear	Temperature: ~		58
Estimated date of last storm 0.25" or greater		5/31/2021			
Item Number	Deficiency/ Corrective Action				
1	Repair/replace downed silt fence on both East ends of the property, or Spread gravel stabilization.				
2	SWPPP not up-to-date. Operator's signature missing from self-inspection reports. Operator didn't sign SWPPP. NOI missing from SWPPP (Tab 3 is empty).				
3	Posting still includes Snyder's permit coverage which has been terminated. Delete Snyder from the sign.				
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports		Latest report Date:	11/11/2021	

Notes:	There isn't a deligation of authority. Stabilization of east lot in progress.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: James Hughes (505) 924-3420
jhughes@cabq.gov

11/16/2021
James D. Hughes