\$2	INSPECTIONS PLUS
-----	------------------

Weather Event Inspection Mixed Use Alameda Development Inspector: Site Name: Jeff Hart 6110 Alameda Blvd NE, Albuquerque, NM 87113 Permit #: C18E086 NMR1001TQ NMR1001U5 Inspection Frequency: Last Rain Event Last Precipitation 48h Forecast **Date of Visit:** May 19, 2021, 8:30:26 AM Wednesday, May 19, 2021, 0.0" Wednesday, May 19, 2021, 0.32"

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

Yes No
Repair silt fence at west pond, approx. 200' blown away from wood stakes. Repair silt fence at the east lot. Approx. 100'.
Yes No
N/A
Yes No
N/A
Yes No
Fabric fence repair at the west pond and

Part 2: Inspection report summary.

- b. Inspection Report Summary
- 1. Qualifications of Inspector:

Training and work experience – see inspector qualification page in the SWPPP.

2. Measures/Areas Inspected:

Site Perimeter, Paved access points, Surrounding inlets, Outfalls, Ponds.

3. Observed Conditions:



Weather Event Inspection

Site Name:	Site Name: Mixed Use Alameda Development 6110 Alameda Blvd NE, Albuquerque, NM 87113		r: Jeff Hart	
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:		
Date of Visit:	May 19, 2021, 8:30:26 AM	Last Rain Event Wednesday, May 19, 2021, 0.0"	Last Precipitation 48h Foreca Wednesday, May 19, 2021, 0.32"	
Minor silt fe	ence repairs required.			
4. Changes N	ecessary to the SWPPP:		2 4 4 0 4 0 4 0 5 0 5 0 5 0 5 0 5 0 5 0 5	
			O changes to the SWPPP or additional MP's required at this time.	
= 114				
5. Were there any discharges?			s No	
NI (
Notes:		De	esignated ponding area only.	
6 What did th	e water look like at the time of the discha			
o. What uld th	e water look like at the time of the discha-	ch	leck_box Clear	
		ch Pari	neck_box_outline_blank	
			neck_box_outline_blank y sandy	
Notes:				
		N/A	A	
7. Was Inspect 1/4"?	ction Conducted Within 24 Hours of Last	Rainfall Over	s No	
Notes:			U 5 105/40/04 0.00W NOAA	
			eather Event 05/18/21= 0.32" per NOAA eather mapping at the time of inspection.	
8. How much did	d it rain?			
Reference precip	pitation values included with this form.			
Notes:				



Certification & Signatures

Certification Statement:

"l certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.â€□

Εl	ectro	onic	Sig	nati	ure

X Jeff Hart Date May 20, 2021 at 9:14:06 AM MDT

Title
Senior Inspector

INSPECTIONS PLUS							
Weather Event Inspection							
Site Name:	Mixed Use Alameda Development 6110 Alameda Blvd NE, Albuquerque, NM 87113	Inspector:	Jeff Hart				
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:					
Date of Visit:	May 19, 2021, 8:30:26 AM	Last Rain Event Wednesday, May 19, 2021, 0.0"	Last Precipitation Wednesday, May 19, 2021, 0.32"	48h Forecast			

There Are No Action Items